

KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

M (65) 9807 3304 Mr. Yap

Date: 29/05/2023

F (65)

Email : kyautosg@gmail.com

FBQ4557X - YAMAHA SNIPER

Damaged Area:

SUPPLEMENTARY ITEMS

Parts / Material :

1	Front Brake Master Pump	Cu7	\$	162.00	✓
2	Gear Shift Lever	Buf nlc	\$	150.00	X

Parts :	\$	312.00
Less Parts 10% :	\$	31.20
Total Parts :	\$	280.80

Special Net Items :

IU unit	Cu7	\$	175.00	✓ S/N
Rear Box	Cu7	\$	450.00	300 S/N
Total S/N Parts :	\$	625.00		

Labour :

Total Labour : \$ -

TOTAL PARTS :	\$	280.80
TOTAL SPECIAL NET ITEM:	\$	625.00
TOTAL LABOUR :		
TOTAL REPAIR COST :	\$	905.80