


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 08.05.2023

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLP7421X**
MODEL : **TOYOTA WISH**
DATE OF ACCIDENT : 02.05.2023
TIME OF ACCIDENT : 16:45 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 1,164.70	\$ 1,164.70
2	FRONT BUMPER FOGLAMP LH <i>3mm</i>	1	\$ 245.80	\$ 245.80
3	FRONT BUMPER FOGLAMP COVER LH	1	\$ 125.10	\$ 125.10
4	FRONT BUMPER FOGLAMP RING LH <i>new</i>	1	\$ 131.20	\$ 131.20
5	FRONT BUMPER FOGLAMP SIDE GRILLE LH <i>Rehnd</i>	1	\$ 87.30	\$ 87.30
6	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 82.90	\$ 165.80
7	FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 335.00	\$ 335.00
8	FRONT BUMPER SPONGE <i>Rehnd</i>	1	\$ 176.80	\$ 176.80
9	HEADLAMP <i>cut - KH</i>	2	\$ 896.40	\$ 1,792.80
10	FRONT GRILLE <i>Rehnd</i>	1	\$ 385.10	\$ 385.10
11	AIR DUCT (INLET) <i>new new</i>	1	\$ 86.00	\$ 86.00
12	FRONT SUPPORT PANEL <i>new</i>	1	\$ 1,156.32	\$ 1,156.32
13	FRONT SUPPORT PANEL TOP COVER GARNISH	1	\$ 155.00	\$ 155.00
14	BRACE PANEL <i>new new</i>	1	\$ 115.00	\$ 115.00
15	FRONT FENDER LH <i>new new</i>	1	\$ 844.10	\$ 844.10
16	FRONT FENDER COWLING LH <i>new new</i>	1	\$ 180.00	\$ 180.00
17	ENGINE UNDER COVER <i>new new</i>	2	\$ 187.00	\$ 374.00

TOTAL PRICE \$ 7,520.02
LESS 25% \$ 1,880.01
SUB TOTAL PRICE \$ 5,640.02

3017.50
2263.12

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLP7421X**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : 02.05.2023
 TIME OF ACCIDENT : 16:45 HOURS

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTALS/NETT
1	FRONT BUMPER CLIP (SET) <i>XLW</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
2	FRONT BUMPER GRILLE CLIP (SET) <i>HLW</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
3	ENGINE UNDER COVER CLIP <i>HLW</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
4	FRONT FENDER COWLING RH CLIP (SET) <i>HLW</i>	1	\$ 80.00	\$ 80.00 <i>+</i>

30 TOTAL \$ 260.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,400.00	<i>300</i>
2	TO SPRAY PAINT	\$ 1,000.00	<i>400</i>
3	TUFF COAT	\$ 250.00	<i>30</i>
4	WIRING, BULB CHECKING	\$ 180.00	<i>30</i>
5	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>+</i>
6	TO CHECK DIRECTORIES OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>+</i>

\$ 3,090.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,900.02
 TOTAL LABOUR COST : \$ 3,090.00
 TOTAL REPAIR COST : \$ 8,990.02

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
K/S 08/05/23
04 Days

Total: 3053.12
L/S: 241C