

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 08 May 2023

Preliminary Advice

Vehicle No	: SCJ3838S	Accident Date	: 26/04/2023
Make	: LOTUS ELISE	Policy No.	:
			PER/AIS/2022/0002465
Assignment Date	: 05/05/2023	Excess	: S\$5,000.00
Date of Inspection	: 5/5/2023	Est. Duration of Repair	: 15
Inspection At	: MOVA AUTOMOTIVE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	97,484.00
Revised Amount	:S\$	93,847.00
Check Items (Estimated)	:S\$	1,007.00
Total	:S\$	94,854.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	176,000.00
COE / PARF Rebate	:S\$	39,409.00
Salvage Value	:S\$	
Margin for Repair	:S\$	136,591.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .