

ASS. REC. BY:

REF: U02/ 23004595/KV

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s KICITM

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 7BA

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 873K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1.61 % 3 Val.: Yes or No

CA /  REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SFD 6969Z Yr Regn: 12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon

Make: Subaru Forester c.c. 1998

Colour: M.D. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 111895 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JFIS JSKC 5JG 102317

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  Inorder / Jammed / Leaked / Burnt or

Brake:  Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD /  A/Rim or

Tyre Size: F: 225/55R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 3 mm R/Bal. 3 mm

L/Bal. 3 mm L/Bal. 3 mm

D.O.A. 29/4/23 D.O.I. 8/5/2023

Survey held at \_\_\_\_\_

Des. of Damages:  Frit / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

W/esp said part by part, unable to locate 2nd parts

Date/Time, File Pass to?

: Prell. Report

: Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transporter:

S - RS - SI

FINANS

Others

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

金興(興)汽車私人有限公司  
**K. KIM HIN AUTO PTE LTD**  
 160 Sin Ming Drive #02-18/19/20  
 Sin Ming AutoCity  
 Singapore 575722  
 Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : DHOM110171451903  
 Accident Date : 29-Apr-2023

No. : 32910  
 Date : 03-May-2023

Our Ref : 023239 / THERESA

PAGE : 1

LIM ENG CHEONG (MR)  
 C/O UNITED OVERSEAS INSURANCE LIMITED  
 146 ROBINSON ROAD  
 #02-01  
 UOI BUILDING  
 Singapore 068909

*NOT Authorized  
 H.H. & I.B.I  
 Recovery After Pain  
 6 days Ex TBA*

ESTIMATED COST OF REPAIR FOR SUBARU FORESTER 2.0I-L CVT (2017) SFD6969Z  
 =====

1 pc front bumper					
1 pc front bumper tow cover					
2 pcs front bumper side retainer (LH/RH)	@ S\$ 18.00		CM 36.00	c	✓
2 pcs front bumper fog lamp (LH/RH)	@ S\$185.00		DI 370.00	c	X
2 pcs front bumper fog lamp chrome moulding (LH/RH)	@ S\$ 45.00		DI 90.00	c	
2 pcs front bumper nozzle cover (LH/RH)	@ S\$ 50.00		DI 100.00	c	✓
2 pcs front bumper nozzle pump (LH/RH)	@ S\$100.00		DI CM 200.00	c	2x NI 7
2 pcs front bumper nozzle pump bracket (LH/RH)					
1 pc front bumper nozzle pump hose					
1 pc front bumper centre intake cover					
1 pc front bumper absorber					
1 pc front bumper reinforcement					
16 pcs front bumper clips	@ S\$ 2.00		CM 125.00	c	✓
1 pc bonnet			DI 270.00	c	✓
1 pc bonnet lock-lower			NI 32.00	c	✓
1 pc bonnet lock catch-upper			DI 580.00	c	✓
2 pcs bonnet hinges (LH/RH)			DI 65.00	c	✓
1 pc bonnet lock:pull cable	@ S\$ 40.00		DI 40.00	c	✓
1 pc bonnet insulation			DI 80.00	c	✓
			CM 60.00	c	✓
			CM 100.00	c	✓

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : DHOM110171451903  
Our Ref : 023239

Page : 2  
No. : 32910

7 pcs bonnet insulation clips	@ S\$ 2.50	<i>nu</i>	17.50	c	<i>✓</i>
1 pc bonnet lock pull cable clip		<i>nu</i>	6.00	c	<i>✓</i>
1 pc bonnet outer chrome		<i>CM</i>	145.00	c	<i>✓</i>
1 pc front grille c/w lower chrome		<i>CM</i>	260.00	c	<i>✓</i>
2 pcs front grille side stopper	@ S\$ 6.50	<i>nu</i>	13.00	c	<i>X</i>
1 pc front grille inner lower bracket			35.00	c	<i>7</i>
1 pc front grille inner upper bracket			30.00	c	<i>7</i>
1 pc front grille centre assy		<i>CM</i>	150.00	c	<i>✓</i>
10 pcs front grille clips	@ S\$ 2.50	<i>nu</i>	25.00	c	<i>✓</i>
2 pcs horn	@ S\$ 45.00		90.00	c	<i>7</i>
2 pcs headlamp assy (LH/RH)	<i>CM</i> @ \$1700.00		3,400.00	c	<i>✓</i>
2 pcs headlamp lower bracket (LH/RH)	@ S\$ 40.00	<i>dsc CM</i>	80.00	c	<i>4</i>
1 pc wiper washer tank		<i>su</i>	115.00	c	<i>X</i>
1 pc front support panel assy		<i>su</i>	380.00	c	<i>✓</i>
1 pc front support lower member			150.00	c	<i>7</i>
1 pc transmission oil cooler			295.00	c	<i>7</i>
1 pc transmission oil cooler inlet hose		<i>su</i>	55.00	c	<i>X</i>
1 pc transmission oil cooler outlet hose		<i>su</i>	55.00	c	<i>X</i>
1 pc air con condenser		<i>B1/Pu</i>	420.00	c	<i>✓</i>
1 pc air con liquid pipe			135.00	c	<i>7</i>
1 pc air con fan cowling		<i>CM</i>	65.00	c	<i>✓</i>
1 pc air con fan blade			60.00	c	<i>7</i>
1 pc air con fan motor			190.00	c	<i>7</i>
1 pc air con fan belt			65.00	c	<i>7</i>
1 pc air con compressor			980.00	c	<i>7</i>
1 pc radiator		<i>Huis CM</i>	520.00	c	<i>✓</i>
1 pc radiator spare tank		<i>su</i>	65.00	c	<i>X</i>
1 pc radiator top hose		<i>pu</i>	40.00	c	<i>✓</i>
1 pc radiator lower hose			40.00	c	<i>7</i>
1 pc radiator fan cowling		<i>CM</i>	65.00	c	<i>✓</i>
1 pc radiator fan blade			55.00	c	<i>7</i>
1 pc radiator fan motor			195.00	c	<i>7</i>
1 pc main pulley			160.00	c	<i>7</i>

Con't Page 3 ...

金興(興)汽車私人有限公司  
**K. KIM HIN AUTO PTE LTD**  
 160 Sin Ming Drive #02-18/19/20  
 Sin Ming AutoCity  
 Singapore 575722  
 Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : DHOM110171451903  
 Our Ref : 023239

Page : 3  
 No. : 32910

1 pc tensioner pulley		120.00	c	7
1 pc tensioner bearing		65.00	c	7
1 pc alternator top cover		80.00	c	7
1 pc air intake duct		95.00	c	7
2 pcs air intake duct clip	@ S\$ 2.50	5.00	c	7
1 pc air cleaner box - top		80.00	c	X
1 pc air cleaner box - lower		90.00	c	X
1 pc air resonator box		60.00	c	7
1 pc RH front fender		210.00	c	7
1 pc RH front fender inner shield		85.00	c	X
10 pcs RH front fender inner shield clips	@ S\$ 2.00	20.00	c	X
2 pcs engine mounting (LH/RH)	@ S\$175.00	350.00	c	7
1 pc gearbox mounting		95.00	c	7
1 pc engine under cover - front		135.00	c	7
		-----		
		12,534.50		
	Add 10% :	1,253.45		
		-----		
		13,787.95		

1 pc front number plate		40.00	sn	✓
1 pc transmission oil fluid		90.00	sn	
1 pc radiator coolant		48.00	sn	

To remove, cut out damaged parts.  
 panel beating, welding, align.  
 refix and to renew affected parts.

*Foot*  
 800.00

To remove aircon condenser, pipes  
 and driers. Vaccum and recharge gas

100.00 ✓

To putty and respray on affected  
 portions.

*Pool*  
 900.00

To focus headlamps. To check front  
 wiring and lighting operation.

50.00 *2ol*

Total : S\$15,815.95  
 =====

Singapore Dollars Fifteen Thousand Eight Hundred  
 and Fifteen and Cents Ninety Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 03/05/2023 09:43 (SGT)  
Reported by ..... Both Policyholder and Actual Driver  
Date of Accident ..... 29/04/2023 22:30 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... PIE TOWARDS TUAS BEFORE EXIT 12 (ALJUNIED FLYOVER)  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SFD6969Z

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... LIM ENG CHEONG  
NRIC No ..... SXXXX012F  
Email Address ..... LEC5@HOTMAIL.COM  
Mobile Phone No ..... (Phone) +65-96424015  
Alternative Phone No ..... -

### VEHICLE PARTICULARS

Manufacturer ..... Subaru  
Model ..... Forester  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... -  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1995

### INSURANCE COMPANY

Name of Insurance Company ..... United Overseas Insurance Ltd  
Policy Number / Cover Note Number ..... DHOM110171451903

### DRIVER

Name of Driver ..... LIM ENG CHEONG  
NRIC No ..... SXXXX012F  
Date Of Birth ..... 04/03/1973  
Occupation ..... Indoor

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

**Sketch Plan**



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	
Owner ID:	Singapore NRIC
Vehicle Details	
Vehicle No.:	012F
Vehicle to be Exported:	SFD6969Z
Intended Deregistration Date:	Yes
Vehicle Make:	02 May 2023
Vehicle Model:	SUBARU
Primary Colour:	FORESTER 2.0I-L CVT AWD SR
Manufacturing Year:	Grey
Engine No.:	2017
Chassis No.:	FB20YB95011
Maximum Power Output:	JF1SJSKC5JG102317
Open Market Value:	110.0 kW (147 bhp)
Original Registration Date:	\$13,268.00
First Registration Date:	29 Dec 2017
Transfer Count:	29 Dec 2017
Actual ARF Paid:	0
Intended PARF Rebate Details	\$13,268.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2027
PARF Rebate Amount:	\$9,287.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$23,264.00
<b>Total Rebate Amount:</b>	<b>\$32,551.00</b>

The information contained herein is correct as at 02 May 2023

OK