

 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: (065)\; 62563561\;\; FAX: (065)\; 62564315\;\; FAX: (065)\; 6256415\;\; FAX: (065)\; FAX$ 

### **Immediate Advice**

To: HSBC Life (Singapore) Pte. Ltd. Date: 26/05/2023

### **Survey Details:**

Date of loss	3-May-23	
Date of appointment	5-May-23	
Date of survey	5-May-23	
Location of survey	SPEEDWERKZ PTE LTD	

## **Vehicle Details:**

Claim Type:	Third pa	Third party SKW106C	
Vehicle number	SKW106		
Make and Model	TOYOTA	TOYOTA VELLFIRE (2494	
Date of registration	14/10/2	14/10/2015	
Excess			
Market Value/ Book Value	\$	90,000.00	(est)
Parf/COE Rebate	\$	49,345.00	(est)
Nett Value/ ERV	\$	40,655.00	(est)

## **Repair details:**

Initial Estimate	\$ 42,987.40

# **Proposed/Revised repair cost:**

Parts	\$ 7,800.17
Check items (estimate)	NIL
Labour	\$ 2,210.00
Supplementary	NIL
Total	\$ 10,010.17
Lump Sum(if applicable)	\$ 8,000.00

Number of days for repair	<u>5</u>



 $51\ UBI\ AVE\ 1,\#02-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ \ TEL: (065)\ 62563561\ \ FAX: (065)\ 62564315$ 

# Remarks:

OID REAR-ENDED TP.

# **Mandate:**

Liability(TP)	100%	
Proposed repair cost	\$ 8,000.00	\$ 8,000.00
Loss of use (7DAYS X \$100.00)	\$ 700.00	NIL
Loss of rental (7DAYS X		
\$160.00)(WITH GST)	NIL	\$ 1,209.60
Loss of income	NIL	NIL
LTA/GIA search fees	\$ 26.75	\$ 26.75
Others	NIL	NIL
Proposed Total	\$ 8,726.75	\$ 9,236.35