



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23004659/Rqy3m4 Date: 20/06/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5576S	Veh. Inspected	SNG 5595P
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/04/23/2070	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	08/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS PLUS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	JTDZS3EU40J068245	Colour	GREY
	Odometer	73799 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60R16	FIRENZA	6 mm
	L/H Front Tyre	205/60R16	FIRENZA	6 mm
	R/H Rear Tyre	205/60R16	FIRENZA	6 mm
	L/H Rear Tyre	205/60R16	FIRENZA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/04/2023	Inspection Date	08/05/2023
	Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	