TOMALULTANTO

TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

ALLIANZ INSURANCE SINGAPORE PTE TLD 79, ROBINSON ROAD #09-01 SINGAPORE 068897 04 May 2023

Attn: MOTOR CLAIMS DEPT

Dear Sirs / Madam.

RE: ACCIDENT INVOLVING VEHICLE NO.: GBG7454S & XE4913D ON 16/03/2023 @ 10:30 HRS ALONG NO.1 BANYAN PLACE

We hereby authorized by our client MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE LTD, the owner/driver of the above mentioned vehicle No.: GBG7454S

We notice that the above accident was caused by your insured/driver negligent driving and/or management of motor vehicle No.: XE4913D

Therefore we are instructed by our client to claim against you/your insured driver in connection with the above captioned accident involving our client's vehicle No.: **GBG7454S** and vehicle No.: **XE4913D** by your insured/driver at the material time. As a result, our client's vehicle was damaged and our client has been put to loss and expenses. Please assign your surveyor to inspect the above mentioned vehicle in the next 48hrs. Filling which, we will proceed to the repair of the vehicle. Details of claim will submitted to you in due course.

The vehicle is now garage at:

TONG LUCK AUTO PTE LTD

160 Sin Ming Drive

#07-01/06 Sin Ming Autocity

Singapore 575722 Tel: 6250 0088

Your kind attention to the matter would be much appreciated.

Yours faithfully.

TONG LUCK AUTO PTE LTD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

FAX:

1 GATEWAY DRIVE #15-08 WESTGATE TOWER

SINGAPORE 608531

TEL :

ATTN: ACCOUNTS DEPT

YOUR REF NO : XE4913D

CLAIM TYPE : THIRD PARTY

TP INS. CO. : ALLIANZ INSURANCE SINGAPORE PTE TLD

ACCIDENT DATE : 16/03/2023 TP VEH REG NO : XE4913D **ESTIMATE**

NO : QUOT202304-000061(00)

DATE : 04/05/2023
POLICY NO : SP2003902365
VEH REG NO : GBG7454S

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323350255

ENGINE NO : 65195034269879

REG. DATE : 2017

Estimate Repair Cost to Vehicle No: GBG7454S

	Description	Quantity	Unit Price	Amount
			<u>S\$</u>	<u>S\$</u>
102	NET PRICE			
1	Tailgate	1	2,720.00	2,720.00
2	Tailgate weatherstrip	1	238.00	238.00
3	Tailgate inner trimboard	1	140.00	140.00
4	Tailgate trimboard clips	10	10.00	100.00
5	Tailgate centre trim	1	58.00	58.00
6	Tailgate centre trim rivet	5	12.00	60.00
7	Tailgate centre logo	1	56.00	56.00
8	Tailgate 'VITO' emblem	1	73.00	73.00
9	Tailgate '114 CDI' emblem'	1	73.00	73.00
10	Rear end panel - inner	1	365.00	365.00
11	Rear end panel - outer	1	350.00	350.00
12	Rear end panel top garnish	1	215.00	215.00
13	Rear bumper	1	1,698.00	1,698.00
14	Rear bumper reinforcement	1	236.00	236.00
15	Rear bumper side retainer - LH	1	78.00	78.00
16	Rear bumper reflector - RH / LH	2	35.00	70.00
17	Taillamp assy - LH	1	868.00	868.00
18	Taillamp lower garnish - RH / LH	2	158.00	316.00
			_	7,714.00
			Less 10%	771.40
			-	6,942.60
	SPECIAL NET			
19	Rear windscreen sealant	1	60.00	60.00
20	Tailgate 'C&C' emblem	1	38.00	38.00
21	Tailgate '70km/h' sticker	1	25.00	25.00
22	Rear bumper sensor (set)	1	350.00	350.00
				473.00
0.0	LABOUR		450.00	450.00
	To remove and refit rear windscreen glass	1	150.00	150.00
24	To transfer damaged tailgate interior mechanism to new tailgate	1	180.00	180.00
25	To remove and refit rear bumper sensor	1	100.00	100.00
26	To check and rectify wiring system	1	80.00	80.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08

WESTGATE TOWER SINGAPORE 608531

TEL :

FAX:

ATTN: ACCOUNTS DEPT

YOUR REF NO : XE4913D

CLAIM TYPE TP INS. CO.

: ALLIANZ INSURANCE SINGAPORE PTE TLD

: THIRD PARTY

ACCIDENT DATE : 16/03/2023 TP VEH REG NO : XE4913D **ESTIMATE**

NO : QUOT202304-000061(00)

DATE : 04/05/2023
POLICY NO : SP2003902365
VEH REG NO : GBG7454S

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI

PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323350255

ENGINE NO : 65195034269879

REG. DATE : 2017

Estimate Repair Cost to Vehicle No: GBG7454S

	Description	Quantity	Unit Price	Amount
			<u>S\$</u>	<u>S\$</u>
27	To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,500.00	1,500.00
28	To putty and spray paint on affected areas	1	1,500.00	1,500.00
29	To apply rust-proofing on replaced and repaired panels	1	160.00	160.00
			_	3,670.00
			TOTAL	S\$ 11,085.60
		AD	D GST @ 8%	886.85
		GI	RAND TOTAL	S\$ 11,972.45

SINGAPORE DOLLAR ELEVEN THOUSAND NINE HUNDRED SEVENTY-TWO AND CENTS FORTY-FIVE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SJ0G233G000N-02 / JP Knights Pte Ltd ENTRY DATE & TIME: 16/03/2023 15:02 (SGT) SUBMITTED BY: Siti VERSION: 3 (04/05/2023 18:08 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving
- and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident **Exact Location of Accident**

Additional Location Information

Country/State of Loss

16/03/2023 15:02 (SGT)

Actual Driver

16/03/2023 10:30 (SGT)

1 Banyan PI, Singapore 627841

MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE

Singapore

GBG7454S

DETAILS OF OWN VEHICLE

LTD

1XXXXX778Z

too_tong.tan@mercedes-benz.com

Vehicle Registration Number

INSURED/POLICYHOLDER

is company?

Name Of Registered Owner

Company Reg No

Email Address

Mobile Phone No

Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of

accident Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

CC

Mercedes

Benz VITO 114 CDI

(Phone) +65-97366684

(Office) +65-82821711

Employment

No - Claiming third party Commercial vehicle

Auto 2143

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number

DRIVER

Name of Driver NRIC No Date Of Birth

Allianz Insurance Singapore Pte. Ltd.

SP2003902365

AHMAD HAIKAL BIN ISMAIL

SXXXX085I 09/01/1985



Occupation Outdoor
Date Of Driving Pass 15/08/2006

Driving experience 16 YEARS AND 7 MONTHS

Gender Ma

Mobile Number (Phone) +65-97366684

Alt. Phone Number

Email Address too_tong.tan@mercedes-benz.com

Address BLK 911 JURONG WEST STREET 91 #12-295

Address complement

Postcode 640911
Is the driver the policyholder? No
If No, Relationship of the Driver with the Insured Hirer
Does Driver Own Other Vehicles? No

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Hit and run / Vandalism / Damaged whilst parked

Weather Conditions Clear Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

ras the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
Translator's name

Translator's ID

Translator's phone number

Translator's email

Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

ON 16/03/2023 AT ABOUT 10:30HRS VEHICLE A(GBG7454S) WAS PARKED AT 1 BANYAN PLACE. WHEN I CAME BACK ROUGHLY AROUND 1030HRS I NOTICED THAT MY REAR HAS BEEN HIT BY VEHICLE B XE8913D.

NO OTHER VEHICLES INVOLVED NOBODY WAS INJURED

ATTACHMENT(S)

Are accident photos available for attachment?

Yes
Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XE8913D

Vehicle Manufacturer Vehicle Model Vehicle Variant -



Vehicle Colour

Vehicle Category NA / Unknown

Name of Driver KATOEN NATIE(COMPANY)

Contact Number

Address -

Address complement -

Postcode - Insurance Company Name -

Nature Of Damage -

Details of property damaged in accident No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any willful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims.
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(Collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 16/03/2023 1420HRS Witnessed by Reporting Centre Personnel DHIYAA

Sketch Plan



Describe Circumstances of the Accident

ON 16/03/2023 AT ABOUT 0915HRS VEHICLE A(GBG7454S) WAS PARKED AT 1 BANYAN PLACE. WHEN I CAME BACK ROUGHLY AROUND 1030HRS I NOTICED THAT MY REAR HAS BEEN HIT BY AN UNKNOWN VEHICLE.							
NO OTHER VEHICLES							
NOBODY WAS INSUR	EU						
Declaration							
I/We declare the foregoing particulars are true in every respect.							
	Abo	M					
Policyholder's Signature / Date & Time	Driver's Signature (If driver is not the policyholder) / Date & Time 16/03/2023 1420HDS	Witnessed by Reporting Centre Personnel DHIYAA					

^{& Time} 16/03/2023 1420HRS