趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047 Tel: 6484 1626 (24Hrs) Fax: 6484 0465 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0 NOT WHENER URy & Preamy After Kaing 3day

To:	India International Insurance Pte Ltd	Policy No:	Third Party
		_	03.05.2023
-	Accident Date : 23.04.2023	Date:	

数 量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Honda Vezel" Reg. No. SLW3610G Claiming Against Your Insured Veh. No. SLJ3872K	-	
1pc	Grille		CM 365.00
2pcs	Grille Mouldings	90.00	Ma 180.00 —
1pc	Grille Emblem		Me 25.00 -
lpc	Grille Garnish Cover		185.00
pcs	Grille Side Brackets		37.00 7
рс	Front Bumper		Bu 963.00 —
2pcs	Front Bumper Clips	3.80	Ma 45.60 —
рс	Front Bumper Reinforcement		340.00 7
pc	Front Bumper Lower Spoiler		1 372.00 X
pc	Front Bumper Center Air Grille		115.80
oc oc	Front Bumper Fog Lamp RH		356.00 ✗
oc	Front Dummer Fee Lemp Cover DU		49.50 X
	Headlamps (LED)	1,945.00	3,890.00 7
ocs	ricadianipo (225)	80.00	9/1? 160.00 7
cs	Headlamp Lower Retainers	60.00	In 85.00 X
c	Support Center Brace Bracket (Plastic)		7,168.90
	Less 20%		1,433.78
			5,735.12
			CM 45.00 SN
- 1	Front Number Plate		45.00 SN
- 1	Front Bumper Sticker		Max 30.00 SN
	To Conduct Electrical Check, Focus Headlamp		30.00 2
1			550.00 3
	Labour Charge - Panel Beating, Repairing Of Bonnet, Support		550.00
- 1	Panel & Part Replacement		110
			44
1	To Respray Affected Areas (2K-Matt Finish)		600.00
			1
- 1	To Reseal Paint Protection (Diamondbrite Ceramic) to Spray Paint Ar	eas	nn 400.00
- 1	LKK Auto Consultants hence notify		7,000,40
	the Repairer of the following:	Total:	7,390.12
- 1	To resurvey before/after spray painting		
	To display damaged part(s) during resurvey		
	Dade prices are subject to a street t		37
- 1	Parts prices are subject to confirmation Third parts suppose an additional area.		
1	Third party survey is on a "Without Prejudice" basis No illegal modification (a) in the property of t	. (
	 No illegal modification(s) is allowed 	1	A.
	 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Compan 	,	
	Acknowledged by Repairer		E and the
1			
	Signature:		
	Date:		