

Mei Kwan (LKKAuto)

From: MG Solution <mg3solution@gmail.com>
Sent: Tuesday, May 9, 2023 9:33 AM
To: Meng Yan (LKK Auto)
Cc: assignments; Mei Kwan (LKKAuto)
Subject: Re: SLW4176L-TOYOTA C-HR (PRE-INSPECTION) ; YOUR REF SNA5711C (AIG)-ACCIDENT ON 06052023
Attachments: GIA REPORT FOR SLW4176L.pdf
Follow Up Flag: Follow up
Flag Status: Flagged
Categories: HMK

Hi All,
Please refer to the GIA REPORT for your reference.
We would like to check liability for this case.

Thank you.

Best Regards,

Ms Hong
MG Solution Pte Ltd
E: mg3solution@gmail.com
T: 6744 4986 / 6744 4165
23 Kaki Bukit Avenue 4 #04-01 Singapore 415933

On Mon, May 8, 2023 at 3:53 PM Meng Yan (LKK Auto) <mengyan@lkkauto.com> wrote:

Dear Ms Hong,

Noted, we will arrange accordingly.

Best Regards,

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 / Whatsapp call: 87813698 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: MG Solution <mg3solution@gmail.com>

Sent: Monday, May 8, 2023 3:31 PM

To: assignments <assignments@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Subject: SLW4176L-TOYOTA C-HR (PRE-INSPECTION) ; YOUR REF SNA5711C (AIG)-ACCIDENT ON 06052023

Dear Sir/Madam,

**ACCIDENT INVOLVING SLW4176L & SNA5711C ALONG
BAYFRONT AVENUE TOWARDS TEMASEK AVENUE BEFORE RAFFLES AVENUE ON 06/05/2023 AT
ABOUT 23:00 HOURS**

A copy of the GIA is attached and please arrange for **PRI-Inspection**. (CAR IN)

Please kindly let us know the liability of this case and provide us a copy of your insured statement and sketch plan for documentation.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that said vehicle can be inspected at:

Workshop: MG Solution Pte Ltd

Address: 23 Kaki Bukit Avenue 4, Vicom Inspection Centre, #04-01 Singapore 415933

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Ms Hong

MG Solution Pte Ltd

E: mg3solution@gmail.com

T: 6744 4986 / 6744 4165

23 Kaki Bukit Avenue 4 #04-01 Singapore 415933

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. They must not be distributed without consent. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.