## ST Powered Motoring Pte Ltd

128 Woodlands Industrial Park E5 Singapore 757851 Tel: 91005500

Email: stpmotoring@gmail.com

Date: 06/05/2023

To: Motor Claims Department China Taiping Insurance

RE: Estimate repair cost of SMR903X

Your Insured: SNE2924D

Dear Sir/Madam,

Vehicle No: SMR903X

Make Model: Toyota / Alphard Date of accident: 05/05/2023

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Akid 8700 5631

Qty	Description	Unit Price	TOTAL	_
1	Front right door SCRIDT		\$ 1,456.98	<b>_</b>
1	Front right door outer garnish BR		\$ 456.70	1
1	Front right door window regulator DMG	Market Control	\$ 589.30	275.9
	Sub-total before discount		\$ 2,502.98	2189.
	Parts percentage discount 20% 25%			547-3
	PARTS TOTAL		\$ 2,002.38	1642
	LABOUR CHARGES & MISC			1
1	Labour to dismantle & replaced all accident			1,
	damaged parts		\$ 600.00	300
2	Labour to putty & spray painting on the accident damaged parts &	- (		1.5
	replaced parts		\$ 500.00	
	LABOUR TOTAL		\$ 1,100.00	
	LABOUR & PARTS TOTAL		\$ 3,102.38	21921

Regards, Terrence Lim

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: