

ASS. REC. BY:

REF:

A15/ 23.004705/ky

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: _____

06 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

08/12/28

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

STJ 9145

Yr Regn: _____

09, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toy Esting

c.c

2362

Colour: _____

White

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

250002

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

ACR 50

0 75058

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

225/30R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Road Stone

Front

Rear

R/Bal. _____

9

mm

R/Bal. _____

9

mm

L/Bal. _____

9

mm

L/Bal. _____

9

mm

D.O.A. _____

3/5/23

D.O.I. _____

9/5/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

From person can pay??

19/5

11pm @ 38501 Cash

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

HWA SENG SPRAY PAINTING PTE LTD
 160 Sin Ming Drive
 #05-11 Sin Ming Autocity
 SINGAPORE 575722
 (COMPANY REGISTRATION NO.: 202017045G)
 TEL : 64533100
 FAX : 62669932

Date of Accident: 03/05/2023

Your Insured

Vehicle No.: SNF 2183 U

NOT Notified
 U/Rap @ 3950/-
 Moving After Paint - 6 days

ESTIMATE REPAIR COSTS TO TOYOTA ESTIMA REG. NO. : SJJ 914 S

			S\$
1pc	Front Bumper	845.10	CM 2727.40 ✓
1pc	Front Grille		Sm 677.60 X
1pc	Front Bumper Reinforcement		R 582.30 ✓
1pc	Front Bumper Sponge		CM 85.90 ✓
2pcs	Headlamp Bracket	(\$22.30/pc)	Sm 44.60 X
1pc	Front Bumper Lower Grille		Sm 229.40 X
2pcs	Front Bumper Retainer	(\$124.30/pc)	Dr 248.60 ✓
1pc	Engine Lower Cover		Sm 236.60 X
1pc	Rear Bumper	780.40	CM 1578.00 ✓
1pc	Rear Bumper Sponge		CM 85.90 ✓
2pcs	Rear Bumper Retainer (Long)	(\$62.50/pc)	Sm 125.00 X
2pcs	Rear Bumper Retainer (Short)	(\$43.80/pc)	Sm 87.60 X
2pcs	Rear Bumper Reflector	(\$65.00/pc)	Sm 130.00 X
1pc	End Panel	645.10	Ry 817.00 ✓
1pc	Emblem Logo		Na 72.20 ✓
1pc	Emblem 'ESTIMA'		Na 53.20 ✓
1pc	Emblem 'AERAS'		Na 62.00 ✓
1pc	Rear End Panel Top Garnish		Sm 378.90 X
1pc	Rear End Panel Lower Garnish		Sm 209.70 X
1pc	Upper Lock		R 361.60 X
1pc	Striker		R 73.70 X
1pc	Taillamp Left		Sm 555.70 X
			9422.90
	Less : 25%		2355.73

7067.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HWA SENG SPRAY PAINTING PTE LTD

160 Sin Ming Drive

#05-11 Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO.: 202017045G)

TEL : 64533100

FAX : 62669932

ESTIMATE REPAIR COSTS TO TOYOTA ESTIMA REG. NO. : SJJ 914 S

SUPPLEMENTARY PARTS

S\$

1pc Air-Con Condenser

Less : 25%

TOTAL

Pr

1216.10 ✓

304.03

912.07

HWA SENG SPRAY PAINTING PTE LTD

