



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopteitd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : ALLIANZ INSURANCE SINGAPORE PTE. LTD.
 12 MARINA VIEW
 #14-01 ASIA SQUARE TOWER 2
 SINGAPORE 018961
 TEL: 6714 3369
 ATTN: Motor Claim Department

Estimate No: ES2300053
 Date: 04 May 2023
 Policy No:
 Veh Reg No: SKV3803J
 Make/Model: VOLKSWAGEN
 TOURAN 1.6 TDI AT
 1T332Z HID FL
 Chassis No: WVGZZZ1TZFW084026
 Engine No: CAYBF7537
 Reg. Date: 15/09/2015

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 01/05/2023
 TP Veh Reg No: SMD9024Y

Not Authorised
11 By B
Accruing After Rain
2-3 days

Estimate Repair Cost to Vehicle No :SKV3803J

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 REVERSE SENSOR - LH	395.00	1 PC	<i>Pa</i> 395.00 X	
2 REVERSE SENSOR - RH	395.00	1 PC	<i>Pa</i> 395.00 X	
			790.00	790.00
Spare Parts				
3 REAR BUMPER	1,985.90	1 PC	<i>Bu</i> 1,985.90 ✓	
4 REAR BUMPER BRACKET - LH	103.00	1 PC	<i>Pa</i> 103.00 X	
5 REAR BUMPER BRACKET - RH	103.00	1 PC	<i>Pa</i> 103.00 X	
6 REAR BUMPER CLIPS	100.00	1 SET	<i>Pa</i> 100.00 ✓	
7 REAR BUMPER INNER GARNISH	265.00	1 PC	<i>Pa</i> 265.00 7	
8 REAR BUMPER LOWER GARNISH	755.20	1 PC	<i>Not</i> 755.20 X	
9 REAR BUMPER REFLECTOR - LH	198.00	1 PC	<i>Pa</i> 198.00 X	
10 REAR BUMPER REFLECTOR - RH	198.00	1 PC	<i>Pa</i> 198.00 X	
11 REAR BUMPER REINFORCEMENT	984.50	1 PC	<i>Pa</i> 984.50 7	
12 REAR BUMPER SIDE RETAINER - LH	123.00	1 PC	<i>Pa</i> 123.00 X	
13 REAR BUMPER SIDE RETAINER - RH	123.00	1 PC	<i>Pa</i> 123.00 X	
14 REAR END PANEL	952.00	1 PC	<i>K</i> 952.00 X	
15 REAR END PANEL TOP GARNISH	325.10	1 PC	<i>Pa</i> 325.10 X	
16 REAR END PANEL TOP GARNISH CLIPS	80.00	1 SET	<i>Pa</i> 80.00 X	
			6,295.70	6,295.70
Labour				
17 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	800.00	1 JOB	800.00 <i>200</i>	
18 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	800.00	1 JOB	800.00 <i>220</i>	
19 TO APPLY RUST- PROOFING ON REPAIRED REPLACED PANEL.	120.00	1 JOB	<i>na</i> 120.00 X	
20 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00 <i>15</i>	
21 COMPUTER DIAGNOSTIC	250.00	1 PC	<i>na</i> 250.00 X	
			2,050.00	2,050.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: