



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23004717/Uwy3m4 Date: 06/06/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMB 1618Y	Veh. Inspected	SMZ 5903X
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/04/23/7008	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	09/05/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	BMW 640 (A)	c.c	2979
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WBA6A02030DZ10459	Colour	MATT BLACK
	Odometer	142149 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	245/35 ZR20	MICHELIN	6 mm
	L/H Front Tyre	245/35 ZR20	MICHELIN	6 mm
	R/H Rear Tyre	275/30 ZR20	MICHELIN	6 mm
	L/H Rear Tyre	275/30 ZR20	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/04/2023	Inspection Date	09/05/2023
	Survey held at	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	