Remain Francisco F. Co.

# 振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883 Tel: 6747-4810 Fax: 6745-5018 cmmotors@singnet.com.sg

Our ref: EST049/23/CIS Your ref: To be advised

8-May-23

### MS First Capital Insurance Limited

36 Robinson Road #16-01 City House Singapore 068877

### **Attn: Motor Claims Department**

Dear Sir / Mdm

### Re: Estimated cost of repair to Nissan NV350 no: PC6280M

Re: Estimated cost of repair to Nissan NV350 no: PC6280M		
Date of accident: 02-05-2023		
Parts supply (Nett)	S\$	1,227.00
1 pc Front panel Device	34	527.30
1 pc Front grille		89.50
1 pc Front grille emblem		35.00
10 pcs Front grille clips @\$3.50		441.30
1 pc Headlamp L/h Culld		133.50
1 pc L/h step garnish Wissy		161.30
1 pc Front L/h wheel hupcap		180.00
1 pc Front L/h tyre (S/Nett)		541.90
1 pc Front bumper Bstock		311.80
1 pc Front bumper fog lamp L/h		117.50 T
i perione damper to		143.80
1 pc Front bumper L/h bracket		181.90
1 per Front bumper Em Fetamer		705.00
1 pc Front bumper reinforcement		21.00
6 pcs Front bumper clips (255.50		700.30
1 pc Transmission cooler Distorted		144.30
1 pc Transmission cooler cowling		199.50
1 pc Transmission cooler hose		5,861.90
	Less 10%:	(586.19)
S/Nett Items		15.00
1 pc Front panel sticker - Green disc (S/Nett)		120.00 80
1 nc Front I/h door sticker - Certis CISCO (S/Nett)		120.00
1 pc Front L/h door sticker - AUXILIARY POLICE (S/Nett)		20.00
1 pc Front L/h door sticker - Company address (S/Nett)		15.00
1 pc Front L/h door sticker - PTE BUS (S/Nett)		30.00
1 pc Front no. plate (S/Nett)		40.00
1 pc Front windscreen gum (S/Nett)		120.00 70
1 bol Auto transmission fluid	_	5,755.71
		5,155.11

## 振 明 摩 哆 HIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883 Tel: 6747-4810 Fax: 6745-5018 cmmotors@singnet.com.sg

## Re: Estimated cost of repair to Nissan NV350 no: PC6280M

Date of accident: 02-05-2023

Parts supply (Nett)

Balance b/f:

5.755.71 S\$

#### Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To remove and refit of front windscreen

To remove and refit dashboard

To remove & refit transmission cooler

To check wirings.

950.00 800 1,000.00 800 120.00 350.00 60.00 30.00 8,265.71 S\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrin Lj 2/5 09/05/23. 08Pays. Not Anthorised Excess \$1000

#### > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	Company
Owner ID:	882K
Vehicle Details	
Vehicle No.:	PC6280M
Vehicle to be Exported:	No
Intended Deregistration Date:	09 May 2023
Vehicle Make:	NISSAN
Vehicle Model:	NV350 MICROBUS 2.5 4DR 5AT ABS
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	YD25430160A
Chassis No.:	JN1TC2E26Z0015106
Maximum Power Output:	
Open Market Value:	\$30,231.00
Original Registration Date:	19 Sep 2017
First Registration Date:	19 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$1,512.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Sep 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,004.00
COE Rebate Amount:	\$18,306.00
Total Rebate Amount:	\$18,306.00

The information contained herein is correct as at 09 May 2023

### sgcarmart

Q



New Cars Used Cars Car Loan Rental Cars Sell Cars Directory Products Insurance Articles Forum Resources

