

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0406/2023/EQ
DATE : 25-Apr-23
WIP : 17808

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS CLARA YEO XINYING (CLARA YANG XINYING)
ADDRESS : 21 STIRLING ROAD
#15-06
SINGAPORE 148960
TELEPHONE : HP +65 96282236
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210111670-01
VEHICLE NO : **SNC 1899 K**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 23/9/2021
ENGINE NO : DEM 034231
CHASSIS NO : WAUZZZF57NA002203
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Apr-23
PLACE OF ACCIDENT : BLK 630 HOUGANG AVENUE 8 HG34 CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC 1899 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	500
4	TO RESPRAY FRONT BUMPER AND FRONT FENDER.	\$ 2,500.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,972.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 1899 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>sch d</i>	1	\$ 2,642.00	✓	
2	FRONT BUMPER SECURING STRIP <i>neu</i>	1	\$ 42.00	+	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>MP</i>	1	\$ 310.00	+	
4	FRONT BUMPER AIR GUIDE - LH	1	\$ 53.00	+	
5	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 159.00	+	
6	FRONT BUMPER TRIM - LH	1	\$ 57.00	+	
7	FRONT BUMPER GUIDE SECTION - LH	1	\$ 43.00	+	
8	FRONT FENDER - LH <i>Repis</i>	1	\$ 1,258.00	+	
9	FRONT FENDER CLOSING ELEMENT - LH <i>neu</i>	1	\$ 88.00	+	
10	FRONT FENDER BRACKET - LH <i>neu</i>	1	\$ 44.00	+	
11	FRONT FENDER RIVET <i>3 MP</i>	6	\$ 24.00	+	
12	FRONT FENDER BRACE - LH	1	\$ 140.00	+	
13	FRONT FENDER CHROME TRIM - LH <i>neu</i>	1	\$ 181.00	✓	
14	FRONT WHEEL HOUSING LINER - LH <i>neu</i>	1	\$ 322.00	+	
15	FRONT WHEEL SPOILER	1	\$ 87.00	+	
16	FRONT FENDER LEDGE COVER - LONG	1	\$ 42.00	+	
17	FRONT FENDER LEDGE COVER - LH SHORT	1	\$ 19.00	+	
18	FRONT HEADLAMP COVER - LH	1	\$ 52.00	+	
19	HEADLIGHT - LH <i>3 MP</i>	1	\$ 8,666.00	X	
20	LIFT CYLINDER - LH <i>neu</i>	1	\$ 230.00	X	
SUB TOTAL SPARE PARTS		:	\$ 14,459.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 1899 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR - LH	1	\$ 272.00	X
22	FRONT PARKING AID SEAL RING	4	\$ 11.00	X
23	SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 15,242.00	
TOTAL LABOUR CHARGES		:	\$ 5,972.00	
GRAND TOTAL		:	\$ 21,214.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *10/05/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT