



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : HSBC LIFE (SINGAPORE) PTE LTD

19/7/2023

Survey Details:

Date of loss	6-May-23
Date of appointment	10-May-23
Date of survey	10-May-23
Location of survey	GARAGE 13 PTE LTD

Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	SMM 5932E
Make and Model	HONDA ODYSSEY 2.4
Date of registration	2/8/2016
Excess	
Market Value	\$ 80,000.00
Part Rebate	\$ 40,539.00
Nett Loss	\$ 39,461.00

Repair details:

Initial Estimate	\$ -
------------------	------

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	\$ -
Lump Sum(if applicable)	

Number of days for repair	<u>2</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

No GIA Report provided. The estimate repair cost of the damaged vehicle is in the region of \$400 - \$600.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	