



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2303256

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 23/05/2023
Reference CS3/III23004814/Twy3m4
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SLB 2743Z
Insured Veh. SLD 6999R
Claim No. MFL2023D0004918
Policy No. D23MFL0002582
Accident Date 05/05/2023
Inspection Date 11/05/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 11.05.2023 12.15pm	
- Dismantle Inspection 15.05.2023 02.13pm	
Merimen Fee	11.00
Subtotal	131.00
GST (8%)	10.48
Grand Total	141.48

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

SML