

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	23/ALL/OD-257(05)
Policy No:	SP2001919392-01	Date of Loss:	08/05/2023
Vehicle Reg. No.:	SMM7407S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LOW ZHEN YANG		
Driver:	LOW ZHEN YANG		

Make/Model:	HYUNDAI AVANTE, 1.6 (A)	Vehicle Reg. Date:	12/07/2019
Vehicle Colour:	SILVER		
Engine No:	G4FGKU134763	Chassis No:	KMHD841CMKU902441
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Remarks:	VEHICLE IN, KINDLY ARRANGE FOR SURVEY.
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	6,233.70
Miscellaneous Items	65.00
Labour	1,730.00
Paintwork Labour	0.00
Towing	0.00
	Gross Total (\$)
	8,028.70
	+ GST 8.00% (\$)
	642.30
	Nett Amount (\$)
	8,671.00

This claim is handled by: WEN YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 09 May 2023)**Parts:** 143 HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** SME Motor Pte Ltd/SMM7407S/09/05/2023 16:11**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET	0.00	0.00	*780.00 F
2	2		*FRT BONNET HINGES	0.00	0.00	*110.00 F
3	1		*FRT BONNET LOCK	0.00	0.00	*95.00 F
4	1		*FRT GRILLE	0.00	0.00	*580.00 F
5	1		*GRILLE CENTRE LOGO	0.00	0.00	-
6	4		*GRILLE CLIPS	0.00	0.00	*8.00 F
7	1		*FRT BUMPER	0.00	0.00	*330.00 F
8	2		*FRT BUMPER RETAINER	0.00	0.00	*40.00 F
9	10		*FRT BUMPER CLIPS	0.00	0.00	*20.00 F
10	1		*FRT BUMPER INNER SPONGE	0.00	0.00	*105.00 F
11	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*380.00 F
12	2		*HEADLAMP	0.00	0.00	*1,720.00 F
13	1		*HEADLAMP SUPPORT PANEL	0.00	0.00	*350.00 F
14	1		*HEADLAMP SUPPORT TOP GARNISH	0.00	0.00	*85.00 F
15	8		*TOP GARNISH CLIPS	0.00	0.00	*16.00 F
16	1		*AIRCON CONDENSER	0.00	0.00	*250.00 F
17	1		*RADIATOR	0.00	0.00	*280.00 F
18	1		*RH HEADLAMP BRACKET	0.00	0.00	*28.00 F
19	1		*RH AIRCON SIDE DEFLECTOR	0.00	0.00	*40.00 F
20	1		*FRT RH FENDER	0.00	0.00	*450.00 F
21	1		*NUMBER PLATE GARNISH NO STOCK	0.00	0.00	-

F=Franchise part.

Sub Total (S\$)	5,667.00
+ Margin on L,N Items 10.00% (S\$)	566.70
Total Parts (S\$)	6,233.70

SME Motor Pte Ltd/SMM7407S/09/05/2023 16:11. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	NUMBER PLATE	40.00
2	1	RADIATOR COOLANT	25.00
Sub Total (S\$)			65.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00
3	LABOUR CHARGE	New	700.00
4	SPRAY PAINTING	New	900.00
Gross Labour Cost (S\$)			1,730.00

SME Motor Pte Ltd/SMM7407S/09/05/2023 16:11. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >