

## Shiau Chan (LKKAuto)

---

**From:** ying <ying@smemotor.com.sg>  
**Sent:** Monday, 26 June 2023 11:55 AM  
**To:** Shiau Chan (LKKAuto); Gary Seah  
**Cc:** SUR  
**Subject:** Re: Damages photos SMM7407S

Dear Shiau chan,

Amount confirmed, please update in merimen.

thanks & regards

YING

On 26/6/2023 10:55 am, Shiau Chan (LKKAuto) wrote:

> Dear Ying,  
>  
> The REMOVE & REFIX AIRCON AND GAS, we recommend \$80/-.  
>  
> Best Regards,  
> Shiau Chan (Ms) | Case Handler  
> LKK Auto Consultants Pte Ltd  
> Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51,  
> Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)  
>  
> -----Original Message-----  
> From: ying <ying@smemotor.com.sg>  
> Sent: Monday, June 26, 2023 10:54 AM  
> To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Gary Seah  
> <gary.seah@smemotor.com.sg>  
> Cc: SUR <sur@lkkauto.com>  
> Subject: Re: Damages photos SMM7407S  
>  
> Dear Shiau Chan,  
>  
>  
> Lab should be \$1,430.  
>  
>  
> Please re-check.  
>  
>  
> thanks & regards  
>  
> YING  
>

> On 26/6/2023 10:51 am, Shiau Chan (LKKAuto) wrote:

>> Dear Ying,

>>

>> The breakdown of our calculation:

>>

>> Parts: \$6,224.90 (after cost+)

>> SN : \$65.00

>> Labour : \$1,410.00

>>

>> Best Regards,

>> Shiau Chan (Ms) | Case Handler

>> LKK Auto Consultants Pte Ltd

>> Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51,

>> Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

>>

>> -----Original Message-----

>> From: ying <ying@smemotor.com.sg>

>> Sent: Monday, June 26, 2023 10:36 AM

>> To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Gary Seah

>> <gary.seah@smemotor.com.sg>

>> Cc: SUR <sur@lkkauto.com>

>> Subject: Re: Damages photos SMM7407S

>>

>> Dear Shiau Chan,

>>

>>

>> Amount not tally, kindly send your calculation breakdown.

>>

>>

>> thanks & regards

>>

>> YING

>>

>> On 21/6/2023 3:34 pm, Shiau Chan (LKKAuto) wrote:

>>> Dear Ying,

>>>

>>> Without prejudice

>>>

>>> We will be advising our principal a cost of repair of \$7,699.90 before excess \$600.00 & GST with 5 days of repair, subject to their approval.

>>>

>>> Best Regards,

>>> Shiau Chan (Ms) | Case Handler

>>> LKK Auto Consultants Pte Ltd

>>> Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk

>>> 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

>>>

>>> -----Original Message-----

>>> From: ying <ying@smemotor.com.sg>

>>> Sent: Wednesday, June 7, 2023 5:49 PM

>>> To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Gary Seah

>>> <gary.seah@smemotor.com.sg>

>>> Cc: SUR <sur@lkkauto.com>  
>>> Subject: Re: Damages photos SMM7407S  
>>>  
>>> Dear Siau Chan,  
>>>  
>>>  
>>> Please confirm.  
>>>  
>>>  
>>> thanks  
>>>  
>>> ying  
>>>  
>>> On 7/6/2023 11:46 am, Siau Chan (LKKAuto) wrote:  
>>>> Dear Sir/Madam,  
>>>>  
>>>> Re-send.  
>>>>  
>>>> Kindly provide us the final bill & supplier parts invoice for finalise.  
>>>>  
>>>> Best Regards,  
>>>> Siau Chan (Ms) | Case Handler  
>>>> LKK Auto Consultants Pte Ltd  
>>>> Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk  
>>>> 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)  
>>>>  
>>>> -----Original Message-----  
>>>> From: Siau Chan (LKKAuto) <siewsc@lkkauto.com>  
>>>> Sent: Wednesday, May 31, 2023 4:32 PM  
>>>> To: Gary Seah <gary.seah@smemotor.com.sg>; Ying  
>>>> <ying@smemotor.com.sg>  
>>>> Cc: SUR <sur@lkkauto.com>  
>>>> Subject: RE: Damages photos SMM7407S  
>>>>  
>>>> Dear Sir/Madam,  
>>>>  
>>>> Kindly provide us the final bill & supplier parts invoice for finalise.  
>>>>  
>>>> Best Regards,  
>>>> Siau Chan (Ms) | Case Handler  
>>>> LKK Auto Consultants Pte Ltd  
>>>> Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk  
>>>> 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)  
>>>>  
>>>> -----Original Message-----  
>>>> From: Siau Chan (LKKAuto) <siewsc@lkkauto.com>  
>>>> Sent: Wednesday, May 24, 2023 9:50 AM  
>>>> To: Gary Seah <gary.seah@smemotor.com.sg>  
>>>> Cc: SUR <sur@lkkauto.com>  
>>>> Subject: RE: Damages photos SMM7407S  
>>>>  
>>>> Dear Gary,

>>>>  
>>>> Kindly provide us the final bill & supplier parts invoice for finalise.  
>>>>  
>>>> Best Regards,  
>>>> Shiau Chan (Ms) | Case Handler  
>>>> LKK Auto Consultants Pte Ltd  
>>>> Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk  
>>>> 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)  
>>>>  
>>>> -----Original Message-----  
>>>> From: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>  
>>>> Sent: Tuesday, May 16, 2023 10:38 AM  
>>>> To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
>>>> Subject: FW: Damages photos SMM7407S  
>>>>  
>>>>  
>>>>  
>>>> Best Regards,  
>>>> Huey Yon | Case Handler  
>>>> LKK Auto Consultants  
>>>> phone: 6256-3561 | email: hueyyon@lkkauto.com | fax: 6741-4108 Blk  
>>>> 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)  
>>>>  
>>>> -----Original Message-----  
>>>> From: gary.seah@smemotor.com.sg <gary.seah@smemotor.com.sg>  
>>>> Sent: Tuesday, May 16, 2023 10:09 AM  
>>>> To: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>; SUR <sur@lkkauto.com>  
>>>> Subject: Damages photos SMM7407S  
>>>>  
>>>> Dear Huey Yon,  
>>>>  
>>>> Please kindly refer to attached for the damages photos.  
>>>>  
>>>> Thank you  
>>>>  
>>>> Note: To protect against computer viruses, email programs may prevent you from sending or receiving certain types of file attachments. Check your email security settings to determine how attachments are handled.  
>>>>  
>>>> --  
>>>> Best Regards,  
>>>> Gary  
>>>>  
>>>> 1 Kaki Bukit Ave 6  
>>>> Autobay@kaki bukit  
>>>> #02-15/16/17/18  
>>>> S(417883)  
>>>> Office: 67476106