## **LETTER OF UNDERTAKING**

## FOR THE REPAIR OF VEHICLE NO. SMT 5825U

TORTHE REPAIR OF VEHIC	DE NO. BRIT 50250 .
We, the undersigned, confirm that we wil	l undertake to repair the vehicle bearing
Registration No SMT 5825U to it of its	s pre-accident condition, and to the satisfaction
owner, at a total cost not exceedingL_	<u>ump Sum \$200,000.00</u> (before excess)
subject to no breach of Terms & Condition	on of the POLICY, and to the legal requirement
of the local Land Transport Authority (L7	ГА).
There should be no further supplements	ary to the repair cost.
The repair job should not be exceeding N	A days to complete the entire repair.
22/05/2023.	ERKZ PIRETO
Date	Workshop Stamp/ Signature
22/05/2023	Kenneth
Date	Witness by surveyor