NO.93. AIG. SLN5298J ODIERGO Supplementary

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 06 Jul 2023)

Parts:

MERCEDES-BENZ CLA180 1.6 COUPE URBAN (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN5298J)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

0.	Qty Part No.	Particulars		%Disc		
				In 0.00	0.00	*600.00 F
	1	*1 pc turbo inter cooler		By 0.00	0.00	*230.00 F
	1	*2 pcs front bumper reinforcement brackets @ \$115/pc	No. of the State o	em 0.00	0.00	*56.00 F
	1	*2 pcs front radiator side air guards @ \$28/pc		Cm 0.00	0.00	*100.00 F
	1	*2 pcs front grille inner brackets @ \$50/pc	well the state of	CM 0.00	0.00	*40.00 F
u name a name	1	*2 pcs front bumper inner garnishs @ \$20/pc		cm 0.00	0.00	*75.00 F
	1	*1 pc front support LH sponge	1.1	(41 0.00	0.00	*280.00 F
e en oppositioner d'est	1	*1 pc radiator lower cross member	10.6	em 0.00	0.00	*115.00 F
	1	*1 pc front grille logo housing support	MI	(cm) 0.00	0.00	*200.00 F
ano y militariyi	1	*1 pc engine under cover	me	cm 0.00	0.00	*108.00 F
0	1	*1 pc front bumper centre lower grille		CIPI	CONTRACTOR	
F=Franchise part.		And the second s	Cub Tot	al (9\$)		1,804.00
		Sub Total (S\$) + Margin on L,N Items 10.00% (S\$)				180.40
			Total Par	de (99)		1,984.40

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >