



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

SOMPO INSURANCE SINGAPORE PL	INV No.	AC2303372
50 RAFFLES PLACE #03-03	INV Date	29/05/2023
SINGAPORE LAND TOWER	Reference	CS3/SMO23004878/Uwy3e2
SINGAPORE 048623	Code	SMO

### PROFESSIONAL SERVICE FEE

Vehicle No.	SKB 894X
Insured Veh.	GBC 9267Z
Claim No.	CMTD2301839/SYH
Policy No.	
Accident Date	08/05/2023
Inspection Date	18/05/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 19.05.2023)	10.00
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 22.05.2023)	10.00
<b>Subtotal</b>	<b>120.00</b>
<b>GST (8%)</b>	<b>9.60</b>
<b>Grand Total</b>	<b>129.60</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**KHM**