

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Vehicle Number : SNG1201C
Vehicle Model : AUDI A1
Accident Date : 05.08.2017
Original Reg Date : 28.11.2016

Date : 02.05.2023
Chassis : WAUZZZ8X2GB117464
TP Ins. CHINA TAIPING

Xiao Tony

ESTIMATE

1	1 pc	Tailgate <i>Dented</i>		2,110.86	✓
2	1 pc	Tailgate Badge <i>New</i>		143.80	✓
3	1 pc	Tailgate Emblem (TFSI) <i>3 pcs</i>		92.60	✓
4	1 pc	Tailgate Emblem (A1) <i>1 pc</i>		91.70	✓
5	1 pc	Tailgate Wiper Motor <i>New</i>		379.90	+
6	1 pc	Tailgate Opener Switch <i>2 MP</i>		145.80	+
7	2 pcs	Tailgate No. Plate Lamp <i>1 pc</i>	69.80	139.60	+
8	2 pcs	Tailgate Lamp <i>RH 2 included</i>	1,087.60	2,175.20	1087.60
9	2 pcs	Tailgate Lamps Inner Sealer <i>RH New</i>	38.00	76.00	38
10	2 sets	Tailgate Lamps Clips <i>New</i>	25.00	50.00	10
11	2 pcs	Tailgate Stopper <i>New</i>	25.00	50.00	+
12	1 pc	Tailgate Inner Trim <i>included</i>		408.90	✓
13	1 set	Tailgate Inner Trim Clip <i>New</i>		40.00	30
14	1 pc	Tailgate Inner Lock <i>2 MP</i>		198.60	✓
15	1 pc	Tailgate Auto Lock Actuator <i>New</i>		175.80	+
16	1 pc	Tailgate Lock Catch <i>New</i>		69.50	+
17	1 pc	Tailgate Weatherstrip <i>1 pc</i>		195.20	✓
18	2 pcs	Tailgate Hinge <i>2 MP</i>	85.20	170.40	+
19	2 pcs	Tailgate Absorber <i>1 pc</i>	156.00	312.00	+
20	1 pc	Rear Windscreen Inner Seal <i>New</i>		60.00	✓
21	1 pc	Rear Bumper <i>Distorted</i>		1,087.70	✓
22	2 pcs	Rear Bumper Side Retainers <i>New</i>	75.90	151.80	+
23	1 set	Rear Bumper Clips <i>New</i>		50.00	✓
24	1 pc	Rear Bumper Center Retainer <i>included</i>		205.60	✓
25	1 pc	Rear Bumper Reinforcement <i>Dented</i>		489.50	✓
26	1 pc	Rear Bumper Lower Skirt <i>Distorted</i>		592.10	336
27	2 pcs	Rear Bumper Reflector <i>RH included</i>	78.20	156.40	78.20
28	4 pcs	Rear Bumper Reverse Sensor (Original) <i>3 pieces dented</i>	225.60	902.40	676.80
29	4 pcs	Rear Bumper Reverse Sensor Holder <i>New</i>	46.00	184.00	100
30	1 pc	Rear Reverse Sensor wirehardness <i>1 pc</i>		785.60	385
31	2 pcs	Taillamp Panel <i>New New</i>	131.00	262.00	+
32	1 pc	End Panel <i>Dented</i>		1,221.20	895
33	1 pc	End Panel Top Trim <i>Dented</i>		213.80	✓
34	2 pc	End Panel airvent <i>New</i>	156.80	313.60	+
35	1 set	End Panel Top Trim Clips <i>New</i>		30.00	+
36	1 pc	Rear Floor Panel <i>Repair</i>		1,385.60	+

37	1 pc	Rear Floor Panel Top Board <i>Defound</i>		395.00	✓
38	1 pc	Rear Floor Panel Top Tool Sponge <i>Defound</i>		228.90	✓
39	1 set	Rear Key Antenna Sensor <i>new</i>		157.20	+
40	1 pc	Battery Safety Cable <i>new</i>		425.10	+
41	2 pcs	Rear Fender Inner Trim <i>new</i>	485.60	971.20	✓
42	2 sets	Rear Fender Inner Trim Clips <i>new</i>	30.00	60.00	✓
43	1 pc	Rear Speaker Board <i>new</i>		448.60	+
44	1 pc	Rear Exhaust Silencer <i>new</i>		825.80	+
45	2 pcs	Rear Exhaust Mountings <i>new</i>	64.00	128.00	+
46	1 pc	Rear Exhaust Gasket <i>new</i>		56.20	+
47	1 pc	Rear Exhaust Heat Plate <i>new</i>		285.90	+

subtotal 19,099.06
 Less 10% 4,774.77
 total **14,324.30**

Special Nett

1	1 pc	Rear Windscreen Sealant <i>new</i>		80.00	60
2	1 pc	Rear No. Plate with Cover <i>Best</i>		70.00	60
3	1 set	Body Panel Joint Sealant <i>new</i>		150.00	60
4	1 set	FloorPanel insulator pads <i>new</i>		250.00	+

Labour charge

Panel Beating	1,800.00	1000
Spray painting	1,800.00	800
Check Wiring on tailamps	80.00	30
Anti rust	100.00	60
Remove and install rear windscreen.	120.00	✓
Remove and install tailgate part	120.00	60
Remove and install interior upholstery	250.00	60
Remove and install reverse sensor	120.00	50
Remove and install rear exhaust	150.00	+

\$ 19,414.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian
n/s 03/05/23.
06 days

total: 14335.96

n/s 9.5K

9.5K