



Main Office : No. 22, Jalan Kilang, Singapore 169419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPG23001937	Date of Loss:	08/05/2023
Vehicle Reg. No.:	SMX9725C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM SWEE GUAN		
Make/Model:	HYUNDAI AVANTE, 1.6 HD DOHC ABS AIRBAG 2WD (A)	Vehicle Reg. Date:	08/02/2021
Vehicle Colour:	BEIGE	Chassis No:	KMHLN41ETNU142681
Engine No:	G4FMMU240688		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	2,392.50
Miscellaneous Items	0.00
Labour	800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,192.50
+ GST 8.00% (S\$)	255.40
Nett Amount (S\$)	3,447.90

This claim is handled by: BILLY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Tanghin 97495749 / 62763561
w.t. Authorise, EX: to be advise
15/5/23 @ 2:45pm
- 2 days
p/p Resing before paint
tanghin @ khanto.com

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 12 May 2023)

Parts: 143 **HYUNDAI AVANTE 1.6 HD DOHC ABS AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMX9725C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP ASSY RH	0.00	0.00	cut *850.00 F ✓
2	1		*HEADLAMP LOWER BRACKET RH	0.00	0.00	de? *40.00 F ✓
3	1		*RADIATOR GRILLE	0.00	0.00	cut *200.00 F ✓
4	1		*FRONT BUMPER LOGO	0.00	0.00	wa *38.00 F ✓
5	1		*FRONT BUMPER	0.00	0.00	in *350.00 F ✓
6	1		*FRONT BUMPER RETAINER RH	0.00	0.00	de *28.00 F ✓
7	1		*FRONT BUMPER SPONGE	0.00	0.00	de? *85.00 F ✓
8	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	X nn *275.00 FX
9	1		*FRONT BUMPER LOWER GRILLE - CENTER	0.00	0.00	cut *120.00 F ✓
10	1		*FRONT BUMPER LOWER LIP	0.00	0.00	dis *50.00 F ✓
11	1		*FRONT BUMPER AIR GRILLE RH	0.00	0.00	cut *90.00 F ✓
12	10		*FRONT BUMPER CLIPS 1.50 x 10.00 - 15.00	0.00	0.00	wa *20.00 F ✓
13	1		*FRONT BUMPER LOWER GARNISH RH	0.00	0.00	cut *15.00 F ✓
14	1		*FRONT TOW COVER RH	0.00	0.00	X nn *14.00 FX
15	1		*SUPPORT PANEL - CHECK	0.00	0.00	

F=Franchise part.

Sub Total (\$\$)	1961.00	2,175.00
+ Margin on L,N Items 10.00% (\$\$)	196.10	217.50
Total Parts (\$\$)	2157.10	2,392.50

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

SUPPLEMENTARY: IPC FRONT BUMPER BEAM - 180.00 / cra ✓

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK & STRAIGHTEN FRONT BODY MEMBER, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	New	200 400.00
2	SPRAY PAINT FRONT BUMPER, FRONT FENDER RH	New	200 400.00
Gross Labour Cost (S\$)			200 800.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1) PARTS 2157.10
2) LABOUR 400.00
2557.10 P&P

PLEASE ADVISE.
THANK YOU
BUT, YAN



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



(SUPPLEMENTARY)

INSURER:

ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPG23001937	Date of Loss:	08/05/2023
Vehicle Reg. No.:	SMX9725C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM SWEE GUAN		
Make/Model:	HYUNDAI AVANTE, 1.6 HD DOHC ABS AIRBAG 2WD (A)	Vehicle Reg. Date:	08/02/2021
Vehicle Colour:	BEIGE	Chassis No:	KMHLN41ETNU142681
Engine No:	G4FMMU240688		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS

	Amount
Parts	104.50
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	104.50
+ GST 8.00% (\$)	8.36
Nett Amount (\$)	112.86
+ Previous Estimates (\$)	3,519.18
Claim Total (\$)	3,632.04

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 May 2023)

Parts: 143 HYUNDAI AVANTE 1.6 HD DOHC ABS AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMX9725C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	10		*FRONT BUMPER CLIPS (AMEND PRICE)	0.00	0.00 nec	*15.00 F
2	1		*FRONT BUMPER BEAM (AMEND PARTS PRICE)	0.00	0.00 cra ✓	*80.00 F
Sub Total (\$\$)						95.00
+ Margin on L,N Items 10.00% (\$\$)						9.50
Total Parts (\$\$)						104.50

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



松義汽車機件私人有限公司
SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

TAX CASH SALE

REG NO: 200922086G
GST NO: 200922086G

MOVA AUTOMOTIVE PTE LTD (CASH TERMS)
BLK 1008, BUKIT MERAH LANE 3, #01-04.
SINGAPORE 159755

No: CSA23-108004
Date: 19/05/2023 08:58
Account No: M018
Sales Person: Colin
Order By: BILLY
Vehicle No: SMX9725C
P/O No: NU142681

01-51

Page 1 of 1

No.	Part No	Description	Location	Qty	Price	Amount
1	92102-AA130	1. HEAD LAMP ASSY-RH (S MODEL) ###	WH	1	850.00	850.00 ✓
2	86351-AA010	3. GRILLE-RADIATOR ###	WH	1	200.00	200.00 ✓
3	86311-AA000	4. LOGO-FRT BUMPER ###	WH	1	38.00	38.00 ✓
4	86511-AA000	5. BUMPER COVER-FRONT ###	WH	1	350.00	350.00 ✓
5	86552-AA000	6. BRACKET-FRT BUMPER SIDE RH	WH	1	28.00	28.00 ✓
6	86531-AA000	9. GRILLE-FRT BUMPER CTR ###	WH	1	120.00	120.00 ✓
7	86591-AA000	10. LIP-FRT BUMPER LWR	WH	1	50.00	50.00 ✓
8	86564-AA010	11. COVER-FRT FOG LAMP RH	WH	1	90.00	90.00 ✓
9	86595-2T500	12. CLIP-BUMPER ###	WH	10	1.50	15.00 ✓
10	86566-AA000	13. BRACKET-FRT BUMPER RH	WH	1	15.00	15.00 ✓

Sub Total: 1,756.00

Add GST @8%: 140.48

Grand Total: 1,896.48

Goods sold are not returnable

Issued by





松義汽車機件私人有限公司
SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

TAX CASH SALE

REG NO: 200822086G
GST NO: 200822086G

MOVA AUTOMOTIVE PTE LTD (CASH TERMS)
BLK 1008, BUKIT MERAH LANE 3, #01-04.
SINGAPORE 159755

No: CSA23-108013
Date: 19/05/2023 11:25
Account No: M018
Sales Person: Colin
Order By: BILLY
Vehicle No: SMX9725C
P/O No: NU142681

Goods Delivery To: #01-51

Page 1 of 1

No.	Part No	Description	Location	Qty	Price	Amount
1	64127-AA000	5. PANEL-HEAD LAMP SUPT RH	WH	1	40.00	40.00 ✓
2	86520-AA000	7. SPONGE-FRT BUMPER ###	WH	1	85.00	85.00 ✓
3	86571-AA000	9.1 STIFFNER-FRT BUMPER LWR	WH	1	80.00	80.00 ✓

Sub Total: 205.00

Add GST @8%: 16.40

Grand Total: 221.40

Goods sold are not returnable

Issued by

