

TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510

Fax: 67410510

Email: sales@n51.com.sg

Our Ref:

SLL 8302 X

Your ref:

YQ 4316 C

12 May 2023

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : LEE HOW KEE

VEHICLE NUMBER : SLL 8302 X

YOUR INSURED VEHICLE NUMBER : YQ 4316 C

ACCIDENT ON 16 MAR 2023 AT ABOUT 12:55 HOURS

ALONG PIE TWDS CHANGI AFTER MACPHERSON RD

We refer to your email / fax dated **12 May 2023** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK Auto Consultants Pte Ltd** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-17

Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



Twincar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: