

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0460/2023/EQ
DATE : 12-May-23
WIP : 20440

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/5/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR THAM CHING HIONG (TAN JINXIONG)
ADDRESS : 3Q LIMAU GARDEN
SINGAPORE 466050

TELEPHONE : HP +65 97922858
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900247537-02
VEHICLE NO : **SMQ 5039 M**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 21/11/2019
ENGINE NO : CZD 884429
CHASSIS NO : WAUZZZF39L1021914
MILEAGE : 39,833
DATE IN : 11-May-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-May-23
PLACE OF ACCIDENT : MARINA ONE BUILDING CARPARK EXIT WAY

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 5039 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00	✓
4	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,600.00	X
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	1000
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR AND LHS UPPER A-PILLAR.	\$ 4,800.00	1650
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,552.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 5039 M

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,137.00	✓
2	FRONT BUMPER CLOSING ELEMENT - LH ?	1	\$ 70.00	?
3	FRONT BUMPER GRILLE - LH <i>cut</i>	1	\$ 131.00	✓
4	FRONT BUMPER CLOSING ELEMENT ?	1	\$ 224.00	?
5	FRONT BUMPER SPOILER <i>cut</i>	1	\$ 451.00	✓
6	FRONT BUMPER AIR GUIDE GRILLE - LH <i>cut</i>	1	\$ 181.00	✓
7	FRONT BUMPER GUIDE SECTION - LH <i>Repd.</i>	1	\$ 46.00	✓
8	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 1,030.00	+
9	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 145.00	+
10	AIR CONDITIONER STICKER <i>new</i>	1	\$ 9.00	+
11	HORN HIGH TONE - LH <i>new</i>	1	\$ 157.00	+
12	HORN BRACKET - LH <i>new</i>	1	\$ 26.00	+
13	FRONT PARKING AID SENSOR - LH ?	1	\$ 272.00	?
14	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 11.00	✓
15	FRONT BUMPER WIRING SET <i>new</i>	1	\$ 756.00	+
16	FRONT FENDER - LH <i>Distorted</i>	1	\$ 1,530.00	✓
17	FRONT FENDER BRACE - LH <i>Best</i>	1	\$ 104.00	✓
18	FRONT FENDER BRACKET - LH <i>and</i>	1	\$ 55.00	✓
19	FRONT FENDER SEAL - LH ?	1	\$ 43.00	?
20	FRONT WHEEL HOUSING LINER - LH <i>Defunct</i>	1	\$ 281.00	✓
SUB TOTAL SPARE PARTS		:	\$ 6,659.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 5039 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT WHEEL HOUSING LINER COVER - LH <i>new</i>	1	\$	19.00	+
22	HEADLIGHT MOUNTING - LH <i>?</i>	1	\$	140.00	?
23	HEADLIGHT - LH <i>could</i>	1	\$	6,305.00	✓
24	HEADLIGHT HEAT SINK <i>?</i>	1	\$	924.00	+
25	HEADLIGHT POWER MODULE <i>new</i>	1	\$	876.00	+
26	HEADLIGHT HOSE - LH <i>new</i>	1	\$	29.00	+
27	LIFT CYLINDER - LH <i>?</i>	1	\$	244.00	?
28	LIFT CYLINDER HOSE <i>new</i>	1	\$	96.00	+
29	LIFT CYLINDER WASH WATER RESERVOIR <i>?</i>	1	\$	253.00	?
30	LOCK CARRIER <i>new</i>	1	\$	1,497.00	+
31	READY-MIX COOLANT <i>new</i>	6	\$	326.00	+
32	FRONT WHEEL COVER - LH / RH <i>LH could, RH new</i>	2	\$	598.00	✓
33	FRONT WATER DEFLECTOR STRIP - LH <i>new</i>	1	\$	55.00	+
34	FRONT WINDOW GUIDE TRIM STRIP - LH <i>new</i>	1	\$	304.00	X
35	FRONT WINDOW SLOT SEAL TRIM STRIP - LH OUTER <i>new</i>	1	\$	266.00	✓
36	FRONT DOOR COVER - LH <i>new?</i>	1	\$	299.00	*?
37	SUNDRIES <i>?</i>		\$	600.00	✓
TOTAL SPARE PARTS		:	\$	19,490.00	
TOTAL LABOUR CHARGES		:	\$	12,552.00	
GRAND TOTAL		:	\$	32,042.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *12/05/23.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 05 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT