## ALLIED AUTO APPRAISAL

22 Upper Serangoon Crescent #16-53 Singapore 534025

Company Registration No. 53127785B

: SMT 192 U Veh No Our Ref: Allied/TP/22-08004 1-Feb-23 Date Report 2-Aug-22 Date of Accident S V Autoworks Pte Ltd Repairer 5-Aug-22 Date of Survey Address of Inspection

8 Kaki Bukit Ave 4 #02-24 Premier Kaki Bukit Singapore 415875

VEHICLE PARTICULARS & CONDITION

07-Jun-18 Date of Registration 3 SEAT LEON 1.0 TSI 116 Style Make & Model 999 cc Engine c.c. CHZ427108 Engine No 06-Jun-28 COE Expiry Date VSSZZZ5FZJR108039 Chassis No

CONDITION OF VEHICLE

Modification No General Condition Good Yes Air-Conditioner Serviceable Steering Footbrake Serviceable Serviceable Handbrake Good Paint Work Yes Wing Mirror

(The below values represent the remaining tyre treads depth) CONDITION OF TYRES


205/55R16 Rear Tyre Size 205/55R16 Front Tyre Size Rear Left Side 6mm Dunlop 6mm Dunlop Front Left Side Rear Right Side Dunlop 6mm Front Right Side 6mm Dunlop

## GENERAL DESCRIPTION OF DAMAGE

The inspected vehicle sustained damage at the REAR portion.

During visual inspection, our surveyor noted that the rear bumper, rear end panel, tailgate, taillamps and among other parts were affected.

All stated damage is subject to consistency of the accident reports.



Repairer Estimate

11,698.00 Parts 840.00 Nett Item 3.940.00 Labour 16,478.00 Total

**Our Recommendation** 

9,066.90 Parts: Nett Item : 660.00 Labour: 3,440.00

GST (7.00%):

Total: 13,166.90 2,633.38 Less 20%:

10,533.52

Lump Sum (Estimated): 10,250.00

The repairer agree to repair the vehicle on a Lump Sum Basis with our recommendation of SGD 10,250.00 (SGD Ten Thousand Two Hundred and Fifty only) and we are in the opinion the repairer would need about a 6.0 working day period to repair the vehicle.

**Allied Auto Appraisal** 

Surveyed by

Ng Heng Chai Licensed Appraiser

## ALLIED AUTO APPRAISAL

RECO	MMENDED PARTS							
No.	. Descriptions	Condition	Qty	Repairer	Adjusted			
1	REAR BUMPER	Deformed	1	1,957.00	1,450.00	/		
2	REAR BUMPER RETAINER RH	Cut	1	175.00	135.00			
3	REAR BUMPER RETAINER LH	Cut	1	175.00	135.00			
4	REAR BUMPER LOWER GARNISH	Grazed	1	437.00	350.00			
5	REAR BUMPER LOWER GARNISH CHROME	Grazed	1	276.00	230.00		1	
6	REAR BUMPER REINFORCEMENT	Dented	1	730.00	541.00	nr	י ו	
7	REAR BUMPER TOW COVER	Grazed	1	109.00	84.00 🗸	1	•	
8	REAR BUMPER REFLECTOR LH	Cracked	1	218.00	175.25		1	
9	REAR BUMPER REFLECTOR RH	Cracked	1	218.00	175.25			
10	REAR REVERSE SENSOR	Shorted	2	594.00	440.00 🗸			
11	REAR END PANEL	Dented	1	881.00	678.00			
12	REAR END PANEL TOP GARNISH	Cut	1	237.00	190.00	) IN	1	
13	TAILGATE	Dented	1	1,692.00	1,410.00	, B.	•	
14	TAILGATE LOCK	Jammed	1	402.00	298.00	nr	,	
15	TAILGATE REFLECTOR RH	Cracked	1	634.00	470.20	nr	י 1	
16	TAILGATE REFLECTOR LH	Cracked	1	634.00	470.20			
17	TAILLAMP RH	Cracked	1	731.00	585.00			
18	TAILLAMP BRACKET RH	Cut	1	264.00	220.00	h		
19	TAILLAMP LH	Cracked	1	789.00	585.00	\ III \ pr		
20	TAILLAMP BRACKET LH	Cut	1	275.00	220.00			
21	REAR EMBLEM LOGO	Necessary	1	126.00	105.00	> '''	1	
22	REAR EMBLEM 'LEON'	Necessary	1	144.00	120.00	,		
		Sub Total (S\$)	_	11,698.00	9,066.90		0040	
		Discount (0%)		11,058.00	3,000.50		2819 -10%	
		Total Parts (S\$)	_	11,698.00	9,066.90		2537.1	Λ
RECO	MMENDED SPECIAL NETT ITEMS						2007.1	U
No.	Descriptions	Condition		Repairer	Adjusted			
1	REAR NUMBER PLATE WITH HOLDER	Necessary		100.00	80.00	50		
2	REAR BUMPER CLIPS	Necessary		100.00		30		
3	TAILGATE SEALANT	Necessary		120.00	100.00		1	
4	TAILGATE REFLECTOR CLIPS	Necessary		100.00	80.00			
5	TAILLAMP CLIPS LH & RH	Necessary		200.00	160.00	•		
7	REAR END PANEL SEALANT	Necessary		120.00	100.00			
8	REAR END PANEL TOP GARNISH CLIPS	Necessary		100.00	60.00	nr		
_				840.00	660.00			
RECON	MMENDED LABOUR		411	NY TO			80	
No.				Repairer	Adjusted			
1	PANEL BEATING.			2,000.00	1,800.00 4	100		
2	TO CHECK WIRING.			150.00	100.00	50		
3	TO TRANSFER TAILGATE MECHANISM.			150.00	100.00	4		
4	TO TUFF KOTE.			120.00		30		
5	TO R&R REVERSE SENSOR.			120.00		30		
6	SPRAY PAINTING.			1,400.00		00		
			77=	3,940.00	3,440.00	00		
COST	DF CLAIMS		11 19	Repairer	Adjusted		1110	)
1	TOTAL PARTS			11,698.00	9,066.90			
2	TOTAL NETT ITEMS			840.00	660.00			
3	LABOUR & SPRAY			3,940.00	3,440.00			
		Gross Total (S\$):	=	16,478.00	13,166.90			
		GST 7.00% (S\$) :		10,470.00	15,100.50			
		Total Amount (S\$)	_	16,478.00	13,166.90			
		194/	8=			0=0	7.46	
						シフワ	7.10	

3727.10

L/S - 2981.68 = 3000