

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 10/05/2023
To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : 1
Vehicle No : GBF-5538-C
Accident Date : 03/05/2023
Make & Model : NISSAN NV200 1.5 DIESEL G (M) EURO 5
Excess : 0.00
Add Excess : 0.00

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>Nett Item</u>			
1	TAILLAMP RH	272.10	over ✓
1	REAR BUMPER	989.70	de ✓
1	REAR BUMPER RETAINER RH	40.20	run ✓
10	REAR BUMPER CLIPS	40.00	over ✓
1	REAR WHEEL HUB CAP RH	80.00	in ✓
1	REAR FENDER RH		
	Sub Total	1422.00	
	Discount 10% On Parts	(142.20)	
	Labour & Misc		
	LABOUR TO FACILITATE REPAIR	600.00	300
			1381.80
			1243.62

RESTORE

Date : 10/05/2023

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 03/05/2023

Vehicle No : GBF-5538-C Make & Model : NISSAN NV200 1.5 DIESEL G (M) EURO 5

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

TO RESPRAY AFFECTED PORTION

600.00

TO CHECK AND RECONNECT ALL NECESSARY WIRINGS

30.00

Sub Total

1230.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2,509.80

Remarks:

SUB TOTAL

GST 8.0 % 200.78

TOTAL 2,710.58

630
1243.62
630
1873.62
1151450
2 days
X

Surveyor's name:

Tan Jiah 97415749

Principal's name:

ETHOZ Group Ltd

Survey Date & Time:

15/5/23 @ 430pm

1/5 Resurvey after repair
Tan Jiah & 1/11/2023
2 days