

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Priya

Date: 12 Jun 2023

Preliminary Advice

Vehicle No	: SJC4115S	Accident Date	: 05/05/2023
Make	: OPEL ASTRA	Policy No.	: D23MPCM000264
Assignment Date	: 15/05/2023	Excess	: S\$0.00
Date of Inspection	: 16/05/2023	Est. Duration of Repair	: 18
Inspection At	: OPTIMA WERKZ PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	56,035.30
Revised Amount	:S\$	37,668.30
Check Items (Estimated)	:S\$	15,103.00
Total	:S\$	52,771.30
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	48,000.00
COE / PARF Rebate	:S\$	23,019.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,981.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO REPAIR THE VEHICLE AT REPAIR COST \$24,000.00 ON LUMP SUM BASIS.