

Immediate Advice

To : HSBC Life (Singapore) Pte. Ltd.**Date: 16/06/2023**

Survey Details:

Date of loss	12-May-23
Date of appointment	15-May-23
Date of survey	15-May-23
Location of survey	TEAMWORK GARAGE PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SMA3897A
Make and Model	TOYOTA HARRIE (1986cc)
Date of registration	22/6/2016
Excess	
Market Value/ Book Value	\$ 69,000.00 (est)
Parf/COE Rebate	\$ 35,380.00 (est)
Nett Value/ ERV	\$ 33,620.00 (est)

Repair details:

Initial Estimate	\$ 15,472.08
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 8,575.03
Check items (estimate)	NIL
Labour	\$ 2,230.00
Supplementary	NIL
Total	\$ 10,805.03
Lump Sum(if applicable)	\$ 8,600.00

Number of days for repair	<u>5</u>
---------------------------	----------



Remarks:

SMN377K MOVED OUT FROM LEFT SIDE AND HIT ONTO OID TAXI, THE IMPACT CAUSED OID TO HIT TP PARKED VEHICLE WHO WAS ON HIS RIGHT.

Mandate:

Liability(TP)	100%	
Proposed repair cost (WITH GST)	\$ 9,288.00	
Loss of use	NIL	
Loss of rental	\$ 700.00	(7DAYS X \$100.00)
Loss of income	NIL	
LTA/GIA search fees	\$ 26.75	
Others	NIL	
Proposed Total	\$ 10,014.75	