

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

 **6744 0777**

 **6744 2377**

Date: 15th May 2022, Monday

M/s China Taiping Insurance (S) Pte Ltd

C/O LKK Auto Consultants Pte Ltd

By FAX: 6256 4315

Dear Sir / Madam,

REF: Your Insured Vehicle GBG 7956K

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)
ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SJB 5105U & GBG 7956K ON 15/05/2023 Along
UBI AVENUE 1 at 1548 Hrs.**

Our client's vehicle – **SJB 5105U** was damaged in the above accident.

A copy of the Singapore Accident Statement report filed is enclosed.

As a result of the accident, the vehicle has been damaged. **We would like to appoint surveyor from your kind firm to conduct a pre-repair survey of the vehicle within 2 working days before we proceed to repair the damaged vehicle.**

Please be informed that the said vehicle can be inspected at:

Name of Workshop: **Best Solution Autocare Pte Ltd**

Address: **53 Ubi Avenue 1 #03-01 Paya Ubi Industrial Park S(408934)**

Contact Person: **Ms CuiPing**

Telephone No: **6744 0777**

Fax No: **6744 2377**

Email Address: **cui ping@carway.com.sg**

Please note that if we do not receive any reply from you within the stipulated timeline, you will be deemed to have waived your rights to a pre-repair inspection. In view of that, we shall proceed to repair the vehicle without further reference to you.

Thank You

BEST SOLUTION AUTOCARE PTE LTD