



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## PRE-REPAIR INSPECTION REPORT

HSBC LIFE (SINGAPORE) PTE LTD  
10 MARINA BOULEVARD #48-01 MARINA BAY  
FINANCIAL CENTRE TOWER 2 SINGAPORE  
018983  
ATTN: HO WINNIE

Ref: CS3/HSB23004979/Rnp3m4  
Date: 24/05/2023  
Code: HSB

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SH 8028B	Veh. Inspected	SNB 4512L
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S3M04MHA	Excess (\$)	0.00
Assign From	HO WINNIE	Assign Date	15/05/2023


### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA C-HR HYBRID 1.8S CVT	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	ZYX102140090	Colour	GREY
Odometer	121954 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R17	TRIANGLE	6 mm
L/H Front Tyre	215/60R17	TRIANGLE	6 mm
R/H Rear Tyre	215/60R17	TRIANGLE	6 mm
L/H Rear Tyre	215/60R17	TRIANGLE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.	
--	---

### 5. General Information

Accident Date	11/05/2023	Inspect Date / Time	16/05/2023 ( 12:18 PM )
Survey held at	48 TOH GUAN ROAD EAST #02-104 SINGAPORE 608586		
Repairer	LAY AUTO GARAGE PTE LTD		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
-------------------------------------	-----------------------

Report Ref No. CS3/HSB23004979/Rnp3m4

#### Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.