

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 65709
Date Estimated : 19/04/2023
Prepared By : Chua Kee Sin

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Barden Mark Edward
33 Lor Pisang Emas

- ACCOUNT - 40000

Cash Sales - Service
Singapore

Singapore 597850

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME9636B	WBATR920X0LE25888	24/10/2018	X3 xDrive30i	58939

DESCRIPTION

Painting right front A-pillar

Painting right exterior rearview mirror cover

Strighten align on right front A pillar

Replacing the exterior rearview mirror on the front door on the right

Estimation days of repair take 3 working quoted for cash job only
Any addition recommend will inform
customer before carryout necessary repairs

VALUE

442.00

39.00

78.00

130.00

0.00

Total Labour 1: 689.00

DESCRIPTION

RH HEATED OUTSIDE MIRROR MEMORY BUS *CM*SET CAMERA HOLDER EXTERIOR MIRROR *CM*Set of screw *mm*FRT RH DOOR WINDOW FRAME COVER (SW *SCM*)REPAIR KIT CABLE EXTERIOR MIRROR *mm*

QTY

PRIC

VALUE

1 1,591.15

1,591.15

1 47.45

47.45

1 18.25

18.25

1 101.15

101.15

1 73.65

73.65

Total Parts : 1,831.65



Labour 1 : 689.00

Parts : 1,831.65

Labour 2 : 0.00

Excess : 0.00

Total GST @ 8% : 201.65

Grand Total : 2,722.30

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **