




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: KHOR SAW THENG			Ref: CS3/HSB23004995/Kqp3e2 Date: 19/05/2023 Code: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 8327U	Veh. Inspected	SJS 1777S
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S3M04MI0	Excess (\$)	0.00
	Assign From	KHOR SAW THENG	Assign Date	16/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 118I (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WBA1A32090J067719	Colour	METALLIC BLACK
	Odometer	62182 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	GOODYEAR	7 mm
	L/H Front Tyre	225/40 R18	GOODYEAR	7 mm
	R/H Rear Tyre	245/35 R18	GOODYEAR	9 mm
	L/H Rear Tyre	245/35 R18	GOODYEAR	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.			
5. General Information				
	Accident Date	12/05/2023	Inspect Date / Time	17/05/2023 (01:55 PM)
	Survey held at	TOH PAINTING & SERVICES PTE LTD BLK C3, WOODLANDS ROAD #391-C & G YEW TEE INDUSTRIAL ESTATE SINGAPORE 677966		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

Report Ref No. CS3/HSB23004995/Kqp3e2

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

KL

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.