

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III23005012/AQY3M4**Date:** 26/07/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000326_02
Claimant Vehicle No : SLT7617C **Insured Vehicle No :** SMW3320G
 Date of Loss: 13/05/2023 Nature of Claim: TP Claim No: MFL2022D0002517

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT7617C**
 Make & Model: HONDA VEZEL, 1.5 HYBRID X (A) Engine No: LEB5959800
 Reg. Date: 10/11/2017 (Man. Year: 2017) Chassis No: RU31259783
 Colour: Red Odometer: 71293 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
 Front Left Side: Giti 6 mm Rear Left Side: Giti 6 mm
 Front Right Side: Giti 6 mm Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		3,600.00		
Nett Amount (S\$)	0.00	3,600.00	-3,600.00	

INSPECTION

Date of Assignment: 16/05/2023
 Date Inspected: 17/05/2023 Inspected At: HUI HUANG HONG BAO MOTORS
 #02-11 KAKI BUKIT AVENUE 2
 SINGAPORE 417921
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2023)
Parts: M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT7617C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >