



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23005021/Kny3m4 Date: 13/06/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SLR 926S	Veh. Inspected	SLE 3473E
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS23/1553	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	16/05/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA PRIUS (A)	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	ZVW506016584	Colour	METALLIC GREY
	Odometer	240410 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	HANKOOK	8 mm
	L/H Front Tyre	195/65 R15	HANKOOK	8 mm
	R/H Rear Tyre	195/65 R15	HANKOOK	8 mm
	L/H Rear Tyre	195/65 R15	HANKOOK	8 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	14/05/2023	Inspection Date	22/05/2023
	Survey held at	GUAN HIN MOTOR WORKSHOP BLK 10 ANG MO KIO IND PK 2A #02-03 AMK AUTOPOINT SINGAPORE 568047		
<b>5a. Remarks</b>				
	A)REGISTRATION DATE: 18 JUL 2016 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	