ASS. REC. BY: Marcus REF: CS	FC1230	05025	/Uny3		
2	ASSIGNM		1		1
D-A	Veh N	10: 6B	E804L	O Yr Regn: 2	8/103
From: Date:		-		orry / Taxi / Prime M	
Estimated Cost:		Truck / Trail	Ť,	,	
OD / TP) WS / TP RES / OD RES / EVA / INV / MV	113	7		liono c.c	198-
To Inspect Vehicle No: 68380			ayofo V	100	/ Std / NI / NA
at Workshop m/s	Color		29262	T/Radio: Insured	
of		eading	VIGC	1/Radio: Insured	/ Std / Ni / N/
nsured: FSH 1140G	Eng/I	-	7+711	7 . 212 - 1	92920
Policy No.	C/No			T02 P1001	75775
Claims No.		\sim	Fair / Poor / Burn		
Sum Insured: Excess:	Steer		Jammed / Leaked		-
(Client's Record)	Brake	: Inorder /	Jammed / Leaked	d/Burnt or	
Make of Veh:	Modi	: (Nil /S/Rin	m / STD A/Rim		
	Tyre	Size: F:	/	95- R15.	
(Policy Condition)		R:	Ġ.		
Remark: The veh had commenced its	IS OIS BS I	DUN / EXNOV		MIC / OHTSU / PIR	/ SUMI /
repair at the time of inspection.	TO	O / YOKO or	1	tustone	
Bal, or Market Value:	Fron	0		Rear	/ .
IDAC Accident Rport: Consistent? : Yes or No	R/Ba	ı. 6	mm	R/Bal.	2 m
GIA / PR Seen: Consistent? : Yes or No		. 6	mm	L/Bal.	, m
Est. Repairs: days Res.: Yes or N		A. 10/00	123	D.O.I. / 7	15/2
Lum Sum: 20 % 3 Val.: Yes or N	o Surv	ey held at	_		10
Eum Guin.	1		Frt / Rear / O/S	S / N/S / U/C / Root	ftop or
CA / REV / REP. / 24 HRS (Vehic	cle: IN/OUT		20,0/5	A	
,				dy Structure affected	due to collision
Date / Time Action / Instruction	C,				
16-11/2	1		. 7 - 1		
18/23 7/5 \$1300 indent	Juses 1	Ked, #	1754.10, 5	("(")	

Data/Time File Peer to?	D	Of Banair	3		
Date/Time, File Pass to? : Preli. Report		Of Repair:		0	
1) : Final Report	Resu	rvey No. of	irip: 1	Survey Fee:	
Date/Time, File Return to?	Add Fee:	: Site Insp	(\$	Transportation:)S + RS,SI	
2)	Aud ree:	: Interview			
Powert Format	_	: Interview : Tech. Inv) Photos	
Report Format :	<u> </u>	:) Others	
Lump Sum / I.B.I: (\$)		: Weekend	(4))	
3 0				TOTAL	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle
--

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	196N
Vehicle No.:	GBE8041D
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2023
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2599255
Chassis No.:	JTFHT02P100193979
Maximum Power Output:	
Open Market Value:	\$27,741.00
Original Registration Date:	28 Mar 2016
First Registration Date:	28 Mar 2016
Transfer Count:	1
ctual ARF Paid:	\$1,388.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	A.5157
COE Expiry Date:	27 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$45,036.00
COE Rebate Amount:	\$12,881.00
Total Rebate Amount:	\$12,881.00

The information contained herein is correct as at 17 May 2023

ОК

sgcarmart

Post an Ad

Q

8

New Cars Used Cars Car Loan Rental Cars Sell Cars Directory Products Insurance Articles Forum Resources

Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD!

Advertiser Login


Ways of Selling

Low Interest Rate In-House Loan by GV Cars Financing



\$0 Downpayment. Loan by GV Cars Financing at 3.28% p.a. Low Interest Rate. GV Automobile Centre StarAd







Bus and 'medi trips' from ComfortDelGro

ComfortDelGro made a donation to three welfare organisations in the form of a refurbished nine-seater bus and free trips for seniors and their medical escorts.

Read this article



Toyota Hiace 3.0M DX \$41,800 \$11,660 /yr 16-Dec-2016 2,982 cc 151,000 km Van **Available Fuel Type:** Diesel

1 owner. Durable Toyota Hiace 3.0M 5 doors diesel van. Low mileage done only 151,000km. Original paintwork since day 1. Clean pristi...

Posted: 16-May-2023



Toyota Hiace 3.0M DX \$40,800 \$14,350 /yr 21-Mar-2016 2,982 cc - Van Available Fuel Type: Diesel

1 Owner Hiace. 5 Door Manual Big Van. 100% High Loan With Insurance Available. High Value For Your Trade-In Vehicles. Call Now For...

ABWIN (1994) Pte Ltd

Posted: 15-May-2023

Compare



Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J liusbro@ymail.com

Tel: 67411730

ESTIMATE

Name: MS First Capital Insurance Limited

Address Motor Claims Department

36 Robinson Road #16-01

City House

Singapore 068877

Ref Date:

2982 cc

16-05-2023 GBE8041D230510

Ref No: Vehicle No:

Model / Make:

GBE8041D Toyota Hiace

Capacity:

Van Turbo 5DR Manual

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear	Bumper Clips 1 set	\$ 622.10	1	\$ 622.10		X
2		Bumper Clips 1 set	\$ 65.00	1	\$ 65.00	SN	X
3	Rear Lh	Bumper Bracket	\$ 202.00	1	\$ 202.00		X X X
4		Door Side Mirror Assy 34	\$1,165.00	1	\$ 1,165.00		
5		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs	552		\$ 500.00		300
6		To putty & spray painting & including touch up paint on accident affected areas			\$ 500.00		480

Total Parts & Labour of estimate for damaged vehicle

Total amount in Lumpsum Basis for repaired vehicle

Not Autom NA 4/5#1300

SDL

To resurvey before/after spray painting

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed not

Acknowledged by Repairer

3,054.10 \$



Liu's Bro Auto Engrg Wks

9-1165 252