

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 19 May 2023

**Preliminary Advice**

Vehicle No	: SLU3070A	Accident Date	: 13/05/2023
Make	: VOLVO V40	Policy No.	: DMPCSNA00161712201
Assignment Date	: 17/05/2023	Excess	: S\$500.00
Date of Inspection	: 18/05/2023	Est. Duration of Repair	: 0
Inspection At	: AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ) 38 WOODLANDS INDUSTRIAL PARK E1, #05-18 SINGAPORE 757700		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	Total Loss
Revised Amount	:S\$	0.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	29,000.00
COE / PARF Rebate	:S\$	18,728.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,272.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :