



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23005084/Rcy3m4 Date: 30/06/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 5020D	Veh. Inspected	SNF 8933H	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/05/23/2041	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	18/05/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SSANGYONG TIVOLI 1.6D STD	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	KPT30A1USLP325240	Colour	GREY	
Odometer	33331 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	KUMHO	6 mm	
L/H Front Tyre	205/65 R16	KUMHO	6 mm	
R/H Rear Tyre	205/65 R16	KUMHO	6 mm	
L/H Rear Tyre	205/65 R16	KUMHO	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/05/2023	Inspection Date	18/05/2023	
Survey held at	NO. 4 JALAN BESUT SINGAPORE 619557			
Repairer	MOTORWAY CAR CARE CENTRE PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	