



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
C/O SEAH ONG & PARTNERS LLP
36 ROBINSON ROAD #12-03 CITY HOUSE
SINGAPORE 018983

Ref: CS3/ASM22012342/Rnp3-1

Date: 16/06/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8493H	Veh. Inspected	FBT 6693G
Policy No.	VFX/P2419140	Coverage (\$)	0.00
Claim No.	23.30668	Excess (\$)	0.00
Assign From	HENG XINYI (SEAH ONG)	Assign Date	18/05/2023

2. Vehicle Particulars & Condition

	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	2022
	Chassis No. MH3SH182111015907	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/12/2022	Inspection Date	26/05/2023
Survey held at	M 1 MOTORING 411 CHANGI ROAD SINGAPORE 419860		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--