

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO SHA2627D
MAKE HYUNDAI
MODEL IONIQ

DATE: 27.04.23
MVA JUMANI
DOA: 26.04.23

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT DOOR ASSY RH <i>pent</i>			\$1,797.20
1	REAR DOOR ASSY RH <i>pent</i>			\$1,789.90
1	REAR FENDER RH <i>BUL</i>			\$1,768.30
1	ROCKER PANEL RH <i>SCR R x</i>			\$715.60
<i>for</i> 1	REAR BUMPER ASSY <i>REAR R x</i>			\$459.40
1	REAR WHEEL CAP <i>WHL</i>			\$346.40
10	REAR BUMPER CLIPS <i>NEL</i>			\$22.00
SUB TOTAL			5723.80	\$6,898.80
LESS 20%			1144.76	\$1,379.76
DISCOUNTED TOTAL			4579.04	\$5,519.04
FRT DOOR COMFORT LOGO <i>NEL</i>				\$75.00 NET
REAR DOOR APPS <i>NEL</i>				\$80.00 NET
BUMPER MAT <i>NEL</i>				\$50.00 NET
ADVERTISEMENT LOGO <i>NEL</i>				\$400.00 NET
				\$605.00
Labour Charge				
PANEL BEATING				\$1,500.00 1400
SPRAY PAINT				\$1,400.00 1000
TRANSFER DOOR PARTS				\$240.00 60
CHECK WIRING				\$50.00 30
REMOVE/REFIX REAR UPHOLSTERY				\$120.00 40
TUFFF KOTE				\$50.00 30
TOTAL LABOUR				\$3,360.00
ESTIMATE TOTAL			7744.04	\$9,484.04
			26 > 1548.80	
			= 6195.23	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Acknowledged by Repairer
Signature:
Date:

L. Dungs 28/4/23
L/S 3:30pm
J. Wm