

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Job Ref No : **305553252**
Date : **09.05.2023**

FINALIZATION FORM

To : LKK

Fax :

Attn : **IRFAN**

Vehicle Reg No. : SHD3352Z

29.04.2023

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: INCOME **GBK6915P**

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) **Lumpsum Repair (if applicable)**

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$2,000.00

3. Estimated normal period for repairs: **2** **working days.**

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature: _____

Name : NAZ LKK

Date : 4/7/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$26.75/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD3352Z

DATE 29.04.2023

MAKE REG 23.06.2016

CHIANG /CHINA

MODEL HYU- 140

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	HEAD LAMP RH ? <i>CRA</i>			\$1,388.00
1	FRONT BUMPER <i>ST</i> / <i>B4C</i>			\$1,052.20
1	FRONT BUMPER BRACKET RH ? <i>X NW</i>			\$49.20
1	FRONT BUMPER GRILLE RH ? <i>X NW</i>			\$187.20
1	HEADLAMP SUPPORT PANEL <i>X SVC</i>			\$907.40
1	FRONT FENDER RH <i>X X NW</i>			\$663.00
1	FRONT FENDER SHIELD RH <i>X X NW</i>			\$174.00
	SUB TOTAL		3347.60	\$4,421.90
	20.00%		669.52	\$8,884.38
	DISCOUNTED TOTAL		2678.08	\$3,537.52
	Labour Charge			
	Panel Beating			\$840.00 <i>3280</i>
	Spray Painting Charge *			\$800.00 <i>250</i>
	Check wiring /Lighting			\$60.00 <i>30</i>
	Remove/refix AC condenser			\$90.00 <i>X NW</i>
	TOTAL LABOUR			\$1,790.00
	ESTIMATE TOTAL		3238.08	\$5,327.52
		<i>2678.08</i>	<i>647.61</i>	
		<i>T=</i>	<i>2590.46</i>	<i>≈ 2600</i>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the Insurance company.				

Z

2 days 4/5

2/5/23 430pm

1st time

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: