



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23005108/Rvy3m4 Date: 11/07/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBJ 7070A	Veh. Inspected	SFP 2829H
Policy No.		Coverage (\$)	0.00
Claim No.	D23001751MFCV	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	19/05/2023
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E200 AVG	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2130422A232729	Colour	GREY
Odometer	102071 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/45 R18	PIRELLI	6 mm
L/H Front Tyre	245/45 R18	PIRELLI	6 mm
R/H Rear Tyre	245/45 R18	PIRELLI	6 mm
L/H Rear Tyre	245/45 R18	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/05/2023	Inspection Date	19/06/2023
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	