

Our Job Ref No 305553709  
 Date 09.05.23

ComfortDelGro Engineering Pte Ltd  
 59 Loyang Drive Singapore 508969  
 Fax: 6546 8156

**FINALIZATION FORM**

To : LKK Fax : \_\_\_\_\_  
 Attn : Mr IRFAN  
 Vehicle Reg No. SHC7245D Date of Accident : 06.05.23

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to : CHINA -- GBF5887U
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \_\_\_\_\_
  - (b) Labour Charges \_\_\_\_\_
  - Total for Part-By-Part Repair Cost** \_\_\_\_\_
  - (c) Lumpsum Repair (if applicable)  
 Total for Lumpsum repair cost after Less: 20% \$2,950.00 (2,750.00)  
**Final Lumpsum Repair cost** \_\_\_\_\_
3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : \_\_\_\_\_ Signature : [Signature]  
 Name : JUMANI Name : IRFAN NAL LKK  
 Tel : 62148315 Date : 28/05/23  
 Fax : 65468156

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	26.75/2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: \_\_\_\_\_ [Signature]

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO **SHC7245D**  
 MAKE **HYUNDAI**  
 MODEL **I40**

DATE: **08.05.23**  
 MVA **JUMANI**  
 DOA: **06.05.23**

**CHINA**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT BUMPER ASSY <i>Scr</i>			\$1,052.20
10	FRT BUMPER CLIPS <i>Rec</i>			\$22.00
1	FRT FENDER LH <i>Dent</i>			\$663.00
1	HEADLAMP ASSY LH ? <i>scr</i>			\$1,388.00
1	FRT BUMPER SIDE BRACKET LH ? <i>X SVC</i>			\$48.80
	FT BUMPER GRILLE LH ? <i>X SVC</i>			\$187.20
	<b>SUB TOTAL</b>		3,125.20	<b>\$3,361.20</b>
	<b>LESS 25%</b>			<b>\$672.24</b>
	<b>DISCOUNTED TOTAL</b>		2,343.90	<b>\$2,688.96</b>
	<b>Labour Charge</b>			
	PANEL BEATING			\$600.00 <i>560</i>
	SPRAY PAINT			\$600.00 <i>500</i>
	TUFF KOTE			\$50.00 <i>30</i>
	CHECK WIRING			\$50.00 <i>30</i>
	<b>TOTAL LABOUR</b>			<b>\$1,300.00</b>
	<b>ESTIMATE TOTAL</b>		3,463.90	<b>\$3,988.96</b>
			2,771.12	

NET

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*3 days LIS*  
*8/5/23 Juman*  
*230pm*