



Your Ref: S3M04II9

Date: 18<sup>th</sup> July 2023

Our Ref: CS3/HSB23001146/Rvp3e2-1

**M/s HSBC Life (Singapore) Pte Ltd**

10 Marina Boulevard  
#48-01 Marina Bay Financial Centre Tower 2  
Singapore 018983  
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBQ 3109M  
INSURED VEHICLE: SH 9645M  
ACCIDENT DATE: 27/01/2023**

We thank you for your instruction on 17/05/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBQ 3109M from M/s Lee Appraisal Services.
- b) Singapore Accident Statement of Vehicles FBQ 3109M and SH 9645M.
- c) Police Report of Vehicles FBQ 3109M.
- d) Colour damaged vehicle photographs of FBQ 3109M.

Pre-Repair Inspection Date: 06/02/2023 at M/s 20 Bukit Batok Crescent #01-19, Singapore 658080,  
Repairer: Primero Racing.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBQ 3109M  
Make & Model : BMW S1000RR  
Year of Registration : 2013  
Chassis Number : WB1052409DZ038901  
Engine Capacity : 999 cc

2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.