

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI23005130/Kqy3q2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	26/06/2023	
			Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNB 5187K	Veh. Inspected	SLE 86J	
	Policy No.	P10784101R00	Coverage (\$)	0.00	
	Claim No.	C10022361/CD	Excess (\$)	0.00	
	Assign From	MAYBIE CHUA	Assign Date	19/05/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	LEXUS ES300 (A)	c.c	2494	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	JTHBW1GG902053511	Colour	METALLIC RED	
	Odometer	156193 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	MICHELIN	6 mm	
	L/H Front Tyre	215/55 R17	MICHELIN	6 mm	
	R/H Rear Tyre	215/55 R17	MICHELIN	6 mm	
	L/H Rear Tyre	215/55 R17	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	17/05/2023	Inspection Date	22/05/2023	
	Survey held at ALAN'S UNITED AUTO PTE LTD				
		BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: