

AUTOMOBILE HUB

VEHICLE DETAILS		
VEHICLE NO	: SJA4610P 2007 DEC	<i>TP Chassis</i>
VEHICLE MODEL	: MAZDA 3	<i>VERON.</i>
CHASSIS NO	: JM6BK106280368086	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Distal d</i>	1	\$ 976.20	\$ 976.20
2	FRONT BUMPER SIDE HOLDER <i>Distal d</i>	1	\$ 28.70	\$ 28.70
3	FRONT BUMPER LOWER SPOILER <i>cut d</i>	1	\$ 550.40	\$ 550.40
4	FRON BUMPER REINFORCEMENT <i>then</i>	1	\$ 548.40	\$ 548.40
5	FRONT BUMPER SIDE GRILLE <i>new</i>	1	\$ 100.20	\$ 100.20
6	FRONT BUMPER LOWER GRILLE <i>cut d</i>	1	\$ 123.80	\$ 123.80
7	FRONT BUMPER UNDERCOVER <i>then</i>	1	\$ 96.50	\$ 96.50
8	FRONT GRILLE <i>cut d</i>	1	\$ 382.10	\$ 382.10
9	FRONT GRILLE LOGO <i>new</i>	1	\$ 54.90	\$ 54.90
10	HEADLAMP <i>cut d</i>	2	\$ 975.90	\$ 1,951.80
11	HEADLAMP LOWER BRACKET <i>new</i>	2	\$ 53.80	\$ 107.60
12	BONNET <i>Distal d</i>	1	\$ 920.60	\$ 920.60
13	FRONT SUPPORT PANEL <i>new</i>	1	\$ 585.80	\$ 585.80
14	FR JNT FENDER <i>Distal d</i>	1	\$ 398.10	\$ 398.10
15	FRONT FENDER INNER SHIELD <i>Distal d</i>	1	\$ 175.40	\$ 175.40
16	FRONT FENDER BRACKET <i>cut</i>	1	\$ 55.80	\$ 55.80
17	FRONT DOOR WING MIRROR <i>new</i>	1	\$ 389.40	\$ 389.40

TOTAL PRICE: \$ 7,445.70
 LESS 20% \$ 1,489.14
 SUB TOTAL PRICE: \$ 5,956.56

4793.70

3834.86

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS	1 SET	\$ 30.00	\$ 30.00
2	FRONT BUMPER UNDERCOVER CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
3	FRONT GRILLE CLIPS	1 SET	\$ 20.00	\$ 20.00
4	COOLANT <i>new</i>	1	\$ 50.00	\$ 50.00
5	FRONT FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
6	FRONT WHEEL RIM <i>new</i>	1	\$ 850.00	\$ 850.00

TOTAL : \$ 1,000.00

100

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	<i>600</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>600</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>40</i>	

5	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	X	
6	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	\$ 120.00	X	
7	TO REMOVE RADIATOR & TO TOP UP COOLANT	\$ 120.00	X	

TOTAL: \$ 2,990.00

1270

ESTIMATE REPORT

TOTAL PARTS COST: \$ 6,956.56
 TOTAL LABOUR COST: \$ 2,990.00
 TOTAL REPAIR COST: \$ 9,946.56

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

FAX:

total: 5204.96
 L/S: 4150
 05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: