

SMRT Accident Vehicle Repair Estimates

SMRT Auton
60 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera
User ID

Section A - Accident Details

Registration Number	SHB5623P
Case Reference Number	TAX/05/23/2057
Registration Date	29/12/21
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	CHIA AIK KIANG
Type of Accident	Head To Side
Accident Date and Time	19/5/23 2:25 AM
Accident Reported Date and Time	19/5/23 3:51 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118461
Special Instruction to ARC, if any	our taxi sustained damaged on the front left portion of the taxi
Prepared Date and Time	19/5/23 5:29 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,200.00	\$0.00
Total Spray Cost	\$1,086.00	\$0.00
Total Spare Part Cost	\$3,807.00	\$0.00
Total Other Cost	\$1,470.00	\$0.00
TOTAL COST	\$7,563.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	3 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	19/05/2023 5:42 PM	
Signature		

Remarks

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Acknowledged by Repairer
Signature:
Date:

SMRT Accident Vehicle Repair Estimates

SMRT Auton
60 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera
User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicabl
TO REPAIR FRONT LH PORTION	\$1,200.00 <i>800L</i>	
Total Labour	\$1,200.00	

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicabl
TO RESPRAY FRONT BUMPER	\$428.00 <i>220L</i>	
TO RESPRAY FRONT FENDER LH	\$428.00 <i>220L</i>	
TO RESPRAY RIM	\$230.00 <i>60L</i>	
Total Spray Painting & Panel Beating	\$1,086.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicabl
TO WASH AND VACUUM	\$60.00 <i>X</i>	
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00 <i>20L</i>	
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00 <i>30L</i>	
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00 <i>60L</i>	
TO REMOVE AND REFIT TYRE	\$120.00 <i>X</i>	
TO REPLACE SUNDRY PARTS	\$100.00 <i>X</i>	
TO CHECK & RESET SYSTEM FUNCTION	\$350.00 <i>?</i>	
ISOLATED OF (EV) (NET)	\$150.00 <i>✓</i>	
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00 <i>?</i>	
Total Other Costs	\$1,470.00	

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		10509500	BEARING -S/KNU	1.00	\$452.09	10.00	\$406.88	Replace	?
		10361097	FINISHER-FRT FOG LP CVR - LH	1.00	\$47.32	10.00	\$42.59	Replace	?
		10909176	LINER ASM-RR W/H PNL - LH	1.00	\$83.72	10.00	\$75.35	Replace	?
		50004880- SEPP	BRACKET-F/FDR FRT LWR - LH	1.00	\$15.81	10.00	\$14.23	Replace	<i>Dr</i> ✓
		10236735- SEPP	FENDER ASM-FRT - LH	1.00	\$379.80	10.00	\$341.82	Replace	<i>Dr</i> ✓
		10533649	INSULATOR ASM-F/FDR -LH	1.00	\$29.22	10.00	\$26.30	Replace	?
		10516114	INSULATOR ASM-F/FDR MID -LH	1.00	\$8.94	10.00	\$8.05	Replace	<i>Dr</i> ✓
		10325882- SPRP	FASCIA-FRT BPR	1.00	\$721.66	10.00	\$649.49	Replace	<i>Dr</i> ✓
		10446164	FINISHER-FRT BPR LOWER - LH	1.00	\$20.38	10.00	\$18.34	Replace	?
		10361099	COVER-FRT FOG LP - LH	1.00	\$40.25	10.00	\$36.23	Replace	?
		10326366	BRACKET-FRT BPR FASCIA - LH	1.00	\$23.09	10.00	\$20.78	Replace	<i>Dr</i> ✓
		10751567	HEADLAMP ASM -LH	1.00	\$1,098.86	10.00	\$988.97	Replace	?
		10580150	ARM ASM-FRT LWR CONT - LH	1.00	\$400.92	10.00	\$360.83	Replace	?
		10317983	WHEEL FRONT LH	1.00	\$618.08	10.00	\$556.27	Replace	<i>Dr</i> X
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	<i>Dr</i> X
		10361101	GRILLE-FRT BPR FASCIA LOWER	1.00	\$149.03	10.00	\$134.13	Replace	<i>Dr</i> X
Total					\$4,215.91		\$3,807.00		