



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internatio	nale Des Experts E	1 Automo	bile		
	ALLIANZ INSURAI		Ref:	CS3/AIS23005184/Tqp3			
	79 ROBINSON RC #09-01 SINGAPOR		Date:	22/05/2023			
				Code:	AIS		
1.		Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBK 2934K	Veh. Inspected	k	GBK 1005Z		
	Policy No.		Coverage (\$)		0.00		
	Claim No.		Excess (\$)		0.00		
	Assign From	SHANTI	Assign Date		22/05/2023		
2.	Vehicle Particulars & Condition						
	Make & Model		c.c		0		
	Engine No. HIDDEN		Year of Reg.				
	Chassis No.	Colour					
	Odometer	Steering					
	Brakes	Brakes			Modification		
	General						
3.	Conditions of Tyres						
		Size	Make		Balance		
	R/H Front Tyre				mm		
	L/H Front Tyre				mm		
	R/H Rear Tyre				mm		
	L/H Rear Tyre				mm		
4.	Description of Damages						
5.	General Information				00/05/0000		
	Accident Date	18/05/2023	Inspection Date	te	22/05/2023		
	Survey held at	S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST					
5a.	1	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.						