

ASS. REQ. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claim No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLA6658R Yr Regn: 2020 / August

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q3 c.c. 1395

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 35272 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZF33L1117957

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/65R17

R: 215/65R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 24/05/23

Survey held at Premises

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TR Chm</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes ()</u>
	<u>1st Survey : No ()</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS. SI

Photos

Others

Report Form: _____

Inspection / Rpt / C

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0491/2023/EQ
DATE : 23-May-23
WIP : 21888

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/5/2023.

YOUR INSURED VEH NO : SKT 3708 L

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

OWNER'S NAME : MS. TAN SEO HONG (CHEN XIAOFENG)
ADDRESS : 37D PASIR PANJANG ROAD
#04-07, THE FOLIAPE
SINGAPORE 118707
TELEPHONE : HP +65 96854335
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070116740-02
VEHICLE NO : **SLA 6658 R**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 28/8/2020
ENGINE NO : CZD 898229
CHASSIS NO : WAUZZZF33L1117957
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-May-23
PLACE OF ACCIDENT : WEST COAST HIGHWAY,
TRAFFIC LIGHT BY MCDONALD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 6658 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	✓
2	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	X
3	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS FRONT DOOR AND LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	1600
4	TO RESPRAY LHS FRONT DOOR AND LHS REAR DOOR.	\$ 2,500.00	1800
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 7,332.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 6658 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - LH <i>Derf</i>	1	\$ 3,192.00	✓
2	FRONT DOOR OUTER SEAL - LH <i>m</i>	1	\$ 196.00	+
3	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 173.00	✓
4	FRONT DOOR CATCH <i>?</i>	1	\$ 141.00	?
5	FRONT DOOR COVER - LH <i>cut</i>	1	\$ 299.00	✓
6	REAR DOOR - LH <i>Derf</i>	1	\$ 3,313.00	✓
7	REAR DOOR OUTER SEAL <i>m</i>	1	\$ 159.00	✓
8	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 338.00	+
9	REAR DOOR CATCH <i>?</i>	1	\$ 141.00	?
10	REAR SILL PANEL SEAL - LH <i>new</i>	1	\$ 159.00	+
11	REAR DOOR COVER - LH <i>cut</i>	1	\$ 286.00	✓
12	REAR BUMPER SPOILER <i>new</i>	1	\$ 540.00	+
13	REAR WHEEL COVER - LH / RH <i>cut</i>	2	\$ 598.00	299.
14	REAR BUMPER REFLECTOR - LH <i>new</i>	1	\$ 49.00	+
15	REAR ALUMINIUM RIM - LH <i>cut</i>	1	\$ 1,485.00	✓
16	REAR ALUMINIUM RIM RUBBER VALVE <i>new</i>	1	\$ 4.00	+
17	SUNDRIES <i>?</i>		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 11,573.00	
TOTAL LABOUR CHARGES		:	\$ 7,332.00	
GRAND TOTAL		:	\$ 18,905.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
SURVEYED DATE : *24/05/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 05 days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT